

FILE NAME: C:\Users\stazad\AppData\Local\Temp\ApAcPublish_2316013827-16-Set.dwg

PRINTED: 1/28/2025 @ 4:14PM

PLOTTED BY: NAZAD

MATCHLINE SHEET C-03

DELETE FROM CONTRACT
NOT PART OF THIS JOB

SEWER REHABILITATION
STANDARD LEGEND

ABANDONED SERVICE

SERVICE RENEWAL

POINT REPAIRS

SERVICE REPAIRS

PIPE LINING CP

CAPPED SERVICE

PIPE LINING PL

HEAVY CLEANING

REPAIR CLEANOUT

REPAIR MANHOLE

TO BE CCTV

TO BE REHAB'D

- MANHOLE REHABILITATION**
MANHOLE EXTRA DEPTH
- ⑧ 6.1 TO 8.0 DEPTH
 - ⑩ 8.1 TO 10.0 DEPTH
 - ⑫ 10.1 TO 12.0 DEPTH
 - ⑭ 12.1 TO 14.0 DEPTH
 - ⑯ 14.1 TO 16.0 DEPTH
 - ⑳ 18.1 TO 20.0 DEPTH
 - NA UNKNOWN DEPTH

- MANHOLE REPAIRS**
- (A) LOCATE/UNCOVER
 - (B) NON-ENTRY INSPECTION
 - (C) RESET FRAME
 - (D) REPLACE FRAME/COVER
 - (E) REPLACE COVER
 - (F) REPLACE EXISTING WATERTIGHT FRAME & COVER
 - (G) RAISE CASTING
 - (H) MANHOLE REHABILITATION
 - (H2) ADD H2S PROTECTION
 - (J) NEW MANHOLE INSTALLATION
 - (J) ADD BENCH TO MANHOLE BOTTOM
 - (K) PLUG & FILL AROUND PIPES
 - (L) REHAB RISERS
 - (M) MISC. SEE NOTE

- ABBREVIATIONS**
- CCTV - CLEAN AND CCTV LINE
 - CO - REPLACE CLEANOUT
 - CNL - COULD NOT LOCATE
 - CP - CURED-IN-PLACE LINING
 - IPR - INTERNAL POINT REPAIR
 - C/L - CLEAN AND LINE MANHOLE
 - NA - NOT APPLICABLE
 - PE - POLYETHYLENE
 - PL - PIPE LINING
 - PL/B - PIPE BURSTING
 - PL/R - REPLACE PIPE
 - PP - PRIVATE PROPERTY
 - PR - POINT REPAIR
 - PVC - POLYVINYL CHLORIDE
 - SL - SLIPLINING
 - SOS - SERVICES ON SEGMENT
 - SR - SERVICE REPAIR

GRW PROJECT NO. 3827-16

engineering | architecture | geospatial

www.grwinc.com

SANITARY SEWER REHABILITATION
4TH AVENUE WEST / TENNESSEE GAS DRIVE
SANITARY SEWER REHABILITATION
CITY OF LOBELVILLE, TENNESSEE

DESIGNED	RG	RG	RG	RG	
DATE	BY	DATE	BY	DATE	BY

DATE: SEPTEMBER 2024
SCALE: 1:75
SHEET NO. C-02

CONTRACT DRAWINGS

SCALE CHECK: THIS MARK SHOULD MEASURE EXACTLY 1" WHEN PLOTTED