City/Utility: Oliver Spring 5 **LEAK REPORT** Date: 3-17-20 Crew Chief: ______ Sheppard Simmons Leak #: ____ 13 Spears Moody Street Address: 714 Syca More Road Material: Size: Type of Leak: Poly 30" 5/8" Meter Copper 3/4" -10" Meter Yoke 12" Other Galvanized Service Line 16" PVC Valve A/C 18" Fire Hydrant 20" Cast Iron Main Line 24" Ductile Iron Other: Other: Rating (1-5): Blue X on Leak Location Blue Dot on Box Notes: Bue Assaw pand To lacation. Leak Location Sketch: This is calculated at 60 PSI: Gallons Pipe Leak Size Rating Lost/Day 400 1 3,000 2

8.000

15,000

Severe Leak - Repair as soon as

possible (20,000+ per day)

3

4

5