505-341-0109



## **Defect Listing**

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A-1_PS-1		Oliver Springs		Pump Station	Fibreglass Reinforc		Easement/R	Sanitary	
Upstream MH		Total Length		Year Laid	Shape		Location Details		
A-1		34.7			Circular				
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
PS-1		34.7			21	21	N/A		
SPR	N/A	MPR	N/A	PO Number	7-03		Customer GRW Purpose		
ODDI	NI/A	MDDI		4397-03					
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-		Rehabilitation Survey	
OF	PR	Surveyed By		Direction	Date		Media label		
N/	Ά	Charlie_Gordon		Downstream	20151007				
OPRI		Certificate Number		Pre-Cleaning	Time		Weather		
N/A		U-615-07000491		No Pre-Cleaning	12:47		Damp		
		Date C	leaned		End Time		Addition	Additional Info	
						12:51			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-1			-					
0.0 ft.	Water Level				5				
32.8 ft.	Water Level				5				
34.7 ft.	Access Point Manhole				0				
Remarks:	Pump Station 1			•					





## **Image Report 4/Page**


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-1_PS-1	Oliver Springs	Pump Station	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A-1	34.7		Circ	cular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
PS-1	34.7		21	21	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 32.8 ft. Grade: 0

Condition: Water Level Remarks: N/A

USMH: A-1
DSMH: Pump Station 1

Access Point Manhole
Pump Station 1
34.7 ft.

Distance: 34.7 ft. Grade: 0

Condition: Access Point Manhole

Remarks: Pump Station 1



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mate	erial	Location C	Sewer Use
A-1_PS-1		Oliver Springs		Pump Station	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH		Total Length		Year Laid	Shape		Location Details	
A-1		34.7			Circ	ular		
DS Ma	DS Manhole		surveyed	Year Renewed Height		Width	Pipe Joint	
PS	PS-1		1.7		21	21	N/A	
SPR	N/A	MPR	N/A	PO Number			Customer GRW	
SPRI	N/A	MPRI	N/A	4397-03				
SPRI	IN/A	IVIPRI	IN/A	Work Order	Purpose			
QSR	N/A	QMR	N/A	4397-02	Pre-		Rehabilitation Survey	
OF	OPR		yed By	Direction	Da	ate	Media label	
N	N/A		_Gordon	Downstream	20151007			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
N	N/A		7000491	No Pre-Cleaning	12:47		Damp	
		Date C	Cleaned		End	Time	Additional Info	
				12:	12:51			

	Structural Ratings			0	& M Ratin	gs	Com	Combined Ratings		
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
	1	0	0	1	0	0	1	0	0	
	2	0	0	2	0	0	2	0	0	
	3	0	0	3	0	0	3	0	0	
	4	0	0	4	0	0	4	0	0	
	5	0	0	5	0	0	5	0	0	
Continuous Defects  Code ID Length										
	Subtotals	0		Subtotals	0		Subtotals	0		
SUMMARY		pe Rating ural Index	0	Pipe Rating O&M Index		0	Overall Pipe Rating Overall Index		0	
		ick Rating	0000	O&M Qui			Ovrl. Quick Rating		0000	