



Defect Listing

Pipe Segment Refere... A-11_A-10	City Oliver Springs	Street Old Harriman highwa...	Material Fibreglass Reinf...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-11	Total Length 301.3	Year Laid	Shape Circular	Location Details	
DS Manhole A-10	Length surveyed 301.3	Year Renewed	Height 15	Width 15	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Charlie_Gordon	Direction Downstream	Date 20151012	Media label	
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 10:19	Weather Damp	
Date Cleaned			End Time 10:32	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-11									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
298.7 ft.	Water Level				10	<input type="checkbox"/>			
301.3 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-10									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-11_A-10	Oliver Springs	Old Harriman highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH A-11	Total Length 301.3	Year Laid	Shape Circular	Location Details	
DS Manhole A-10	Length surveyed 301.3	Year Renewed	Height 15	Width 15	Pipe Joint... N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-11



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 298.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 301.3 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-10



Albuquerque, NM

SPR	N/A	MPR	N/A	PO Number		Customer	
SPRI	N/A	MPRI	N/A	4397-03		GRW	
QSR	N/A	QMR	N/A	Work Order		Purpose	
				4397-02		Pre-Rehabilitation Survey	
OPR		Surveyed By		Direction	Date	Media label	
N/A		Charlie_Gordon		Downstream	20151012		
OPRI		Certificate Number		Pre-Cleaning	Time	Weather	
N/A		U-615-07000491		No Pre-Cleaning	10:19	Damp	
Date Cleaned					End Time	Additional Info	
					10:32		

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div>CodeIDLength</div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Subtotals			0		Subtotals	0		Subtotals	0		
SUMMARY			Pipe Rating	0	Pipe Rating	0	Overall Pipe Rating	0			
			Structural Index	0	O&M Index	0	Overall Index	0			
			Str. Quick Rating	0000	O&M Quick Rating	0000	Ovrl. Quick Rating	0000			