ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A-14	_A-13	Oliver	Springs	Old harriman HIGHWA	Fibreglass	Reinforc	nforc Easement/R		
Upstre	am MH	Total I	_ength	Year Laid	Shape		Location Details		
A-	-14	3:	25		Circ	ular	r		
DS M	anhole	Length s	surveyed	Year Renewed	Height	Width	Width Pipe Joint		
A-	·13	32	25		15	15	N/A		
SPR	N/A	MPR	25	PO Number			Customer		
				4397-03			GRW		
SPRI	N/A	MPRI	3.1	Work Order	Work Order		Purpose		
QSR	N/A	QMR	4137	4397-02		Pre-	Pre-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Date		Media	label	
2	25	Charlie_	_Gordon	Downstream	2015	1012			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
3.1		U-615-07000491		No Pre-Cleaning	08:47		Damp		
		Date C	leaned	End		End Time Addit		al Info	
					09	:08			

Distance	Condition	Court Diet	Values			laint	Clock Position		
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-14						<u>'</u>		•
0.0 ft.	Water Level				10				
152.8 ft.	Water Level				20				
176.6 ft.	Water Level Sag	S01			35				3
185.6 ft.	Infiltration Stain				0		9	3	
195.9 ft.	Water Level Sag	F01			35				3
208.7 ft.	Water Level				15				
310.8 ft.	Camera Underwater								4
312.3 ft.	Water Level Sag	S02			35				3
325.0 ft.	Water Level Sag	F02			35				3
325.0 ft.	Water Level				5				
325.0 ft.	Access Point Manhole				0				
Remarks:	A-13			•					•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use	
A-14_A-13	Oliver Springs	Old harriman HIGHWA	Fibreglass Reinforc		Easement/R	Sanitary	
Upstream MH	Total Length	Year Laid	Shape		Location	on Details	
A-14	325		Circular				
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint		
A-13	325		15	15	N/A		



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-14



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 152.8 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 176.6 ft. Grade: 3

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-14_A-13	Oliver Springs	Old harriman HIGHWA	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A-14	325		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-13	325		15	15	N/A	,



Distance: 185.6 ft. Grade: 0

Condition: Infiltration Stain

Remarks: N/A



Distance: 195.9 ft. Grade: 3

Condition: Water Level Sag

Remarks: N/A



Distance: 208.7 ft. Grade: 0

Water Level

Remarks: N/A

Condition:

311.0 ft.

Distance: 310.8 ft. Grade: 4

Condition: Camera Underwater

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-14_A-13	Oliver Springs	Old harriman HIGHWA	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A-14	325		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-13	325		15	15	N/A	,



Distance: 312,3 ft. Grade: 3

Condition: Water Level Sag

Remarks: N/A



Distance: 325.0 ft. Grade: 3

Condition: Water Level Sag

Remarks: N/A



Distance: 325.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 325.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-13



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A-14_	_A-13	Oliver	Springs	Old harriman HIGHWA	Fibreglass Reinforc		orc Easement/R Sar		
Upstrea	am MH	Total I	Length	Year Laid	Shape		Location Details		
A-	14	32	25		Circ	cular	ır		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A-	13	32	25		15	15	N/A		
SPR	N/A	MPR	25	PO Number	PO Number		Customer GRW Purpose		
SPRI	N/A	MPRI	3.1	4397-03					
SFRI	IN/A	IVIFKI	3.1	Work Order	Work Order				
QSR	N/A	QMR	4137	4397-02		Pre	e-Rehabilitation Survey		
OF	PR	Surve	yed By	Direction	Di	ate	Media	edia label	
2	5	Charlie_	_Gordon	Downstream	2015	51012			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
3.1		U-615-07000491		No Pre-Cleaning	08:47		Damp		
		Date C	leaned	•	End Time		Additional Info		
					09	:08			

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
				_	_		_	_	4	_	_
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	1	4	4	1	4
			5	0	0	5	0	0	5	0	0
Contin	uous C	Defects									
Code	ID	Length									
MWLS	F01	19.3	0	0	0	3	4	12	3	4	12
MWLS	F02	12.7	0	0	0	3	3	9	3	3	9
			Subtotals	0		Subtotals	8		Subtotals	8	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	25	Overall P	pe Rating	25	
J.	- ·····/ \		Struct	ural Index	0	0	&M Index	3.1	Ove	erall Index	3.1
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	4137	Ovrl. Quick Rating		4137