



Defect Listing

Pipe Segment Refere... A-16_A-15	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-16	Total Length 229.2	Year Laid	Shape Circular	Location Details	
DS Manhole A-15	Length surveyed 229.2	Year Renewed	Height 15	Width 15	Pipe Joint... N/A


SPR N/A	MPR 12	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 4	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 4300		
OPR 12	Surveyed By Charlie Gordon	Direction Upstream	Date 20151012
OPRI 4	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 12:39
	Date Cleaned	End Time 12:49	Weather Damp
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-15									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
11.6 ft.	Camera Underwater				0	<input type="checkbox"/>			4
36.4 ft.	Water Level				10	<input type="checkbox"/>			
109.3 ft.	Camera Underwater				0	<input type="checkbox"/>			4
217.7 ft.	Camera Underwater				0	<input type="checkbox"/>			4
229.2 ft.	Water Level				10	<input type="checkbox"/>			
229.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-16									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-16_A-15	Oliver Springs	Old harriman Highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-16	229.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-15	229.2		15	15	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-15



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 11.6 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Distance: 36.4 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-16_A-15	Oliver Springs	Old harriman Highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-16	229.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-15	229.2		15	15	N/A



Distance: 109.3 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Distance: 217.7 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Distance: 229.2 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 229.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-16



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-16_A-15	Oliver Springs	Old harriman Highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-16	229.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-15	229.2		15	15	N/A
SPR	N/A	MPR	12	Customer	
SPRI	N/A	MPRI	4	GRW	
QSR	N/A	QMR	4300	Purpose	
			4397-02	Pre-Rehabilitation Survey	
OPR	Surveyed By	Direction	Date	Media label	
12	Charlie_Gordon	Upstream	20151012		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
4	U-615-07000491	No Pre-Cleaning	12:39	Damp	
Date Cleaned			End Time	Additional Info	
			12:49		

Page #: 4