505-341-0109



Defect Listing

Pipe Segme	ent Refere	City		Street	Mat	Material		Sewer Use		
A-17_	_A-16	Oliver	Springs	Old Harriman Highwa	Fibreglass	Reinforc Easement/r Sai				
Upstrea	am MH	Total I	_ength	Year Laid	Sh	ape	Location Details			
A-	17	16	8.2		Circ	Circular				
DS Ma	nhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint			
Α-	16	16	8.2		15 15 N/A					
SPR	N/A	MPR	2	PO Number			Customer			
ODDI	NI/A	MDDI		4397-03	4397-03			GRW		
SPRI	N/A	MPRI	2	Work Order			Purpose			
QSR	N/A	QMR	2100	4397-02		Pre	e-rehabilitation Survey			
OF	PR	Surve	ed By	Direction	Da	ate	Media	label		
2	2	Charlie-Gordon		Downstream	20151013					
OP	rRI	Certificate Number		Pre-Cleaning	Time		Weather			
2	2 U-615-07000491		No Pre-cleaning	12:02		Damp				
Date Cleaned				End	Time	Addition	nal Info			
					12	:11				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition	Cont. Dict.	1st	2nd	%	Jonn	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-17								
0.0 ft.	Water Level				10				
71.0 ft.	Water Level Sag	S01			25				2
75.8 ft.	Water Level Sag	F01			25				2
82.6 ft.	Water Level				10				
167.0 ft.	Water Level				10				
168.2 ft.	Access Point Manhole				0				
Remarks:	A-16								





Image Report 4/Page

(Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	A-17_A-16	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Easement/r	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location	Details
	A-17	168.2	168.2 Circular		ular		
	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
	A-16	168.2		15	15	N/A	_



Distance: 0.0 ft. Grade:

Condition: Access Point Manhole

Remarks: A-17



Distance: 0.0 ft. Grade:

Condition: Water Level

Remarks: N/A



Distance: 71.0 ft. Grade: Water Level Sag

Remarks: N/A

Condition:



Distance: 75.8 ft. Grade:

Condition: Water Level Sag

Remarks: N/A






Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-17_A-16	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Easement/r	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A-17	168.2		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-16	168.2		15	15	N/A	



Distance: 82.6 ft. Grade:

Condition: Water Level Remarks: N/A



Distance: 167.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 168.2 ft. Grade: Condition:

Access Point Manhole

Remarks: A-16



PACP Conditions

Pipe Segment Refere		C	ity	Street	Mat	Material		Sewer Use	
A-17_	_A-16	Oliver	Springs	Old Harriman Highwa	Fibreglass	Fibreglass Reinforc		Sanitary	
Upstre	am MH	Total	Length	Year Laid	Shape		Location Details		
A-	17	16	8.2		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A-	16	16	168.2		15	N/A			
SPR	N/A	MPR	2	PO Number	PO Number		Customer GRW		
SPRI	N/A	MPRI	2	4397-03					
SPRI	IN/A	IVIPRI		Work Order		Purpose			
QSR	N/A	QMR	2100	4397-02		Pre-rehabilitation Survey		ırvey	
OF	PR	Surve	yed By	Direction	Date		Media label		
2	2	Charlie-Gordon		Downstream	20151013				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
2	2 U-615-0700049		7000491	No Pre-cleaning	12:02		Damp		
	Date Cleaned			-	End	Time	Addition	nal Info	
					12	:11			

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Norma	al Def	ects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
			4			4			4		
			1	0	0	1	0	0	2	0	0
			2	0	0	2	0	0		0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu Code MWLS	ID F01	Defects Length 4.8	0	0	0	2	1	2	2	1	2
in Ee		110	C		· ·	_	•	_	_	•	-
			Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		 Pi	pe Rating	0	 Pi	pe Rating	2	Overall Pi	ipe Rating	2	
30			Struct	ural Index	0	0	&M Index	2.0	Ove	erall Index	2.0
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2100	Ovrl. Qu	ick Rating	2100