

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A-19_A-18 Upstream MH A-19		Oliver Springs  Total Length  162.4		Old Harriman Highwa	Fibreglass	Fibreglass Reinforc		Sanitary	
				Year Laid	Shape Circular		Location Details		
DS Ma	anhole	Length surveyed 162.4		Year Renewed	Height	Width 15	Pipe Joint N/A		
Α-	18				15				
SPR	N/A	MPR	N/A	PO Number			Customer		
0001	N1/A			4397-03			<b>GRW</b> Purpose		
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre	Pre-rehabilitation Survey		
OF	PR	Survey	red By	Direction	Date		Media label		
N/	<b>'</b> A	Charlie-Gordon		Downstream	20151013				
OP	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A U-615		U-615-0	7000491	No Pre-cleaning		11:22			
Date Cleaned						End Time 11:39		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-19								
0.0 ft.	Water Level				10				
160.2 ft.	Water Level				5				
162.4 ft.	Access Point Manhole				0				
Remarks:	A-18								





## **Image Report 4/Page**


$\overline{}$	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	A-19_A-18	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Easement/r	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location Details	
	A-19	162.4		Circ	ular		
	DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
	A-18	162.4		15	15	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A-19



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 160.2 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 162.4 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-18



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A-19_A-18 Upstream MH A-19		Oliver Springs  Total Length  162.4		Old Harriman Highwa	Fibreglass	Fibreglass Reinforc		Sanitary	
				Year Laid	Shape Circular		Location Details		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	n Pipe Joint		
A-	A-18		2.4		15	15	N/A		
SPR	N/A	MPR	N/A	PO Number				Customer	
SPRI	N/A	MPRI	N/A	4397-03			GRW		
SFRI	IN/A	IVIFKI	IN/A	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre		urvey	
OF	PR .	Surveyed By		Direction	Date		Media label		
N/	/A	Charlie-Gordon		Downstream	20151013				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N/	N/A		7000491	No Pre-cleaning 11		11:22			
		Date C	leaned	End Time 11:39		Additional Info			

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			4			4			4		
			2	0	0	2	0	0	2	0	0
				0	0		0	0		0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu	ous C	Defects									
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SIII	ММΔ	RY	Pi	pe Rating	0	Pi	pe Rating	0	Overall P	pe Rating	0
SUMMARY		Struct	ural Index	0	0	&M Index	0	Overall Index		0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000