



Defect Listing

Pipe Segment Refere... A-20_A-19	City Oliver Springs	Street Old Harriman Highwa...	Material Fibreglass Reinf...	Location C... Easement/r...	Sewer Use Sanitary
Upstream MH A-20	Total Length 168.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-19	Length surveyed 168.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A


SPR N/A	MPR 32	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-rehabilitation Survey	
QSR N/A	QMR 2B00				
OPR 32	Surveyed By Charlie-Gordon	Direction Downstream	Date 20151013	Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning No Pre-cleaning	Time 12:59	Weather Damp	
Date Cleaned			End Time 13:08	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-20									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
17.6 ft.	Water Level Sag	S01			15	<input type="checkbox"/>			2
96.7 ft.	Water Level Sag	F01			15	<input type="checkbox"/>			2
165.6 ft.	Water Level				5	<input type="checkbox"/>			
168.9 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-19									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-20_A-19	Oliver Springs	Old Harriman Highwa...	Fibreglass Reinforc...	Easement/r...	Sanitary
Upstream MH A-20	Total Length 168.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-19	Length surveyed 168.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-20



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 17.6 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A



Distance: 96.7 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... A-20_A-19	City Oliver Springs	Street Old Harriman Highwa...	Material Fibreglass Reinforc...		Location C... Easement/r...	Sewer Use Sanitary
Upstream MH A-20	Total Length 168.9	Year Laid	Shape Circular		Location Details	
DS Manhole A-19	Length surveyed 168.9	Year Renewed	Height 15	Width 15	Pipe Joint...	N/A



Distance: 165.6 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 168.9 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-19



PACP Conditions

Pipe Segment Refere... A-20_A-19	City Oliver Springs	Street Old Harriman Highwa...	Material Fibreglass Reinforc...	Location C... Easement/r...	Sewer Use Sanitary
Upstream MH A-20	Total Length 168.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-19	Length surveyed 168.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A
SPR N/A	MPR 32	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-rehabilitation Survey	
QSR N/A	QMR 2B00				
OPR 32	Surveyed By Charlie-Gordon	Direction Downstream	Date 20151013	Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning No Pre-cleaning	Time 12:59	Weather Damp	
Date Cleaned			End Time 13:08	Additional Info	

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length	0	0	0	2	16	32	2	16	32
MWLS	F01	79.1									
			Subtotals	0		Subtotals	16		Subtotals	16	
SUMMARY			Pipe Rating	0		Pipe Rating	32		Overall Pipe Rating	32	
			Structural Index	0		O&M Index	2.0		Overall Index	2.0	
			Str. Quick Rating	0000		O&M Quick Rating	2B00		Ovrl. Quick Rating	2B00	