



Defect Listing

Pipe Segment Refere... A-27_A-26	City Oliver Springs	Street Old harriman highwa...	Material Fibreglass Reinf...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-27	Total Length 310.4	Year Laid	Shape Circular	Location Details	
DS Manhole A-26	Length surveyed 310.4	Year Renewed	Height 15	Width 15	Pipe Joint... N/A

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Charlie Gordon	Direction Downstream	Date 20151014	Media label	
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 11:21	Weather Damp	
Date Cleaned			End Time 11:31	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-27									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
99.5 ft.	Water Level				10	<input type="checkbox"/>			
144.3 ft.	Water Level				5	<input type="checkbox"/>			
308.7 ft.	Water Level				5	<input type="checkbox"/>			
310.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-26									



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-27_A-26	Oliver Springs	Old harriman highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-27	310.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-26	310.4		15	15	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-27



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 99.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 144.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A-27_A-26	City Oliver Springs	Street Old harriman highwa...	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-27	Total Length 310.4	Year Laid	Shape Circular		Location Details	
DS Manhole A-26	Length surveyed 310.4	Year Renewed	Height 15	Width 15	Pipe Joint...	N/A



Distance: 308.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 310.4 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-26



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-27_A-26	Oliver Springs	Old harriman highwa...	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-27	310.4		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-26	310.4		15	15	N/A
SPR	N/A	MPR	N/A	Customer	
SPRI	N/A	MPRI	N/A	GRW	
QSR	N/A	QMR	N/A	Purpose	
				Pre-Rehabilitation Survey	
OPR	Surveyed By	Direction	Date	Media label	
N/A	Charlie_Gordon	Downstream	20151014		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
N/A	U-615-07000491	No Pre-Cleaning	11:21	Damp	
Date Cleaned			End Time	Additional Info	
			11:31		

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
<div>Continuous Defects</div> <div><div>CodeIDLength</div><div></div></div>			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY			Pipe Rating	0		Pipe Rating	0		Overall Pipe Rating	0	
			Structural Index	0		O&M Index	0		Overall Index	0	
			Str. Quick Rating	0000		O&M Quick Rating	0000		Ovrl. Quick Rating	0000	