



Defect Listing

Pipe Segment Refere... A-28_A-27	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-28	Total Length 311.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-27	Length surveyed 311.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A

SPR	N/A	MPR	10	PO Number 4397-03	Customer GRW
SPRI	N/A	MPRI	2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR	N/A	QMR	2500		
OPR 10	Surveyed By Charlie_Gordon	Direction Downstream	Date 20151014	Media label	
OPRI 2	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 11:52	Weather Damp	
	Date Cleaned		End Time 12:05	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-28									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
169.3 ft.	Water Level				5	<input type="checkbox"/>			
215.7 ft.	Water Level				10	<input type="checkbox"/>			
235.2 ft.	Water Level				5	<input type="checkbox"/>			
279.8 ft.	Water Level Sag	S01			20	<input type="checkbox"/>			2
304.5 ft.	Water Level Sag	F01			20	<input type="checkbox"/>			2
307.6 ft.	Water Level				5	<input type="checkbox"/>			
311.9 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-27									



Image Report 4/Page

Pipe Segment Refere... A-28_A-27	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-28	Total Length 311.9	Year Laid	Shape Circular		Location Details	
DS Manhole A-27	Length surveyed 311.9	Year Renewed	Height 15	Width 15	Pipe Joint...	N/A



Distance: 0.0 ft. Grade: 0
 Condition: Access Point Manhole
 Remarks: A-28



Distance: 0.0 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 169.3 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 215.7 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A




Image Report 4/Page

Pipe Segment Refere... A-28_A-27	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-28	Total Length 311.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-27	Length surveyed 311.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A



Distance: 235.2 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 279.8 ft. Grade: 2
 Condition: Water Level Sag
 Remarks: N/A



Distance: 304.5 ft. Grade: 2
 Condition: Water Level Sag
 Remarks: N/A



Distance: 307.6 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A-28_A-27	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-28	Total Length 311.9	Year Laid	Shape Circular		Location Details	
DS Manhole A-27	Length surveyed 311.9	Year Renewed	Height 15	Width 15	Pipe Joint...	N/A



Distance:	311.9 ft.	Grade:	0
Condition:	Access Point Manhole		
Remarks:	A-27		



PACP Conditions

Pipe Segment Refere... A-28_A-27	City Oliver Springs	Street Old harriman Highwa...	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A-28	Total Length 311.9	Year Laid	Shape Circular	Location Details	
DS Manhole A-27	Length surveyed 311.9	Year Renewed	Height 15	Width 15	Pipe Joint... N/A

SPR N/A	MPR 10	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 2500	Direction Downstream	Date 20151014	Media label	
OPR 10	Surveyed By Charlie_Gordon	Pre-Cleaning No Pre-Cleaning	Time 11:52	Weather Damp	
OPRI 2	Certificate Number U-615-07000491	Date Cleaned	End Time 12:05	Additional Info	

Normal Defects	Structural Ratings			O & M Ratings			Combined Ratings				
	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating		
	1	0	0	1	0	0	1	0	0		
	2	0	0	2	0	0	2	0	0		
	3	0	0	3	0	0	3	0	0		
	4	0	0	4	0	0	4	0	0		
	5	0	0	5	0	0	5	0	0		
Continuous Defects											
Code	ID	Length									
MWLS	F01	24.7	0	0	0	2	5	10	2	5	10
Subtotals			0	Subtotals			5	Subtotals			5
SUMMARY	Pipe Rating		0	Pipe Rating		10	Overall Pipe Rating		10		
	Structural Index		0	O&M Index		2.0	Overall Index		2.0		
	Str. Quick Rating		0000	O&M Quick Rating		2500	Ovrl. Quick Rating		2500		