ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



# **Defect Listing**

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A-31_A-30		Oliver Springs		Old Harriman Highwa	Fibreglass Reinforc		Easement/R	Sanitary	
Upstream MH Tot		Total I	_ength	Year Laid	Sh	ape	Location Details		
A-	31	34	9.1		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A-	30	34	9.1		21 21		N/A		
SPR	N/A	MPR	18	PO Number			Customer		
0001				4397-03		GRW			
SPRI	N/A	MPRI	2	Work Order	Work Order		Purpose		
QSR	N/A	QMR	2900	4397-02		Pre-Rehabilitation Survey		urvey	
OF	PR	Surve	yed By	Direction	D	ate	Media	label	
1	8	Charlie_Gordon		Downstream	20151008				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2		U-615-07000491		No Pre-Cleaning	09:43		Damp		
		Date C	leaned		End Ti		End Time Additiona		
					09	:58			

Distance	Condition	Camt Dfat	Values			laint	Clock Position		0
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-31						'		•
0.0 ft.	Water Level				15				
50.6 ft.	Water Level				5				
112.8 ft.	Water Level Sag	S01			25				2
114.4 ft.	Deposits Settled Compacted				5		5		2
133.3 ft.	Water Level Sag	F01			25				2
144.4 ft.	Water Level				5				
174.8 ft.	Water Level Sag				15				2
208.3 ft.	Water Level				5				
331.9 ft.	Water Level Sag	S02			30				2
346.2 ft.	Water Level Sag	F02			30				2
346.3 ft.	Water Level				10				
349.1 ft.	Access Point Manhole				0				
Remarks:	A-30			•	•				•

The Town of Oliver Springs Clean and CCTV





#### **Image Report 4/Page**


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use		
A-31_A-30	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details			
A-31	349.1		Circular					
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint			
A-30	349.1		21	21	N/A			



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-31



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 50.6 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 112.8 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





#### **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Material		Location C	Sewer Use
A-31_A-30	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details			
A-31	349.1		Circular					
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint			
A-30	349.1		21	21	N/A			



Distance: 114.4 ft. Grade: Condition: **Deposits Settled Compacted** 

Remarks: N/A



Distance: 133.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 144.4 ft. Grade: 0

Condition: Water Level Remarks: N/A



Distance: 174.8 ft. Grade:

Condition: Water Level Sag

Remarks: N/A





#### **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use		
A-31_A-30	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details			
A-31	349.1		Circular					
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint			
A-30	349.1		21	21	N/A			



Distance: 208.3 ft. Grade: (

Condition: Water Level Remarks: N/A



Distance: 331,9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 346.2 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 346.3 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



### Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-31_A-30	Oliver Springs	Old Harriman Highwa	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A-31	349.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-30	349.1		21	21	N/A	ر ا



Distance: 349.1 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A-30



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A-31	_A-30	Oliver	Springs	Old Harriman Highwa	Fibreglass Reinforc		Easement/R	Sanitary
Upstre	am MH	Total	Length	Year Laid	Sh	ape	Location Det	
A-	-31	34	9.1		Circ	ular		
DS Ma	anhole	Length :	surveyed	Year Renewed	Height	Width	Pipe Joint	
A-	-30	34	9.1		21 21		N/A	
SPR	N/A	MPR	18	PO Number			Customer GRW Purpose	
SPRI	N/A	MPRI	2	4397-03				
SFRI	IN/A	IVIFKI		Work Order				
QSR	N/A	QMR	2900	4397-02	. Pr€		re-Rehabilitation Survey	
OI	PR	Surveyed By		Direction	Direction E		Date Media	
1	8	Charlie_Gordon		Downstream	20151008			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
:	2	U-615-07000491		No Pre-Cleaning	09	09:43		
		Date C	Cleaned	End Time		Additional Info		
					09	:58		

			Structural Ratings			0	& M Ratin	gs	Combined Ratings		
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			4	•		4			4		
			1	0	0	2	0	0	2	0	0
			2	0	0		2	4		2	4
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Contin	uous C	Defects									
Code	ID	Length									
MWLS	F01	20.5	0	0	0	2	4	8	2	4	8
MWLS	F02	14.3	0	0	0	2	3	6	2	3	6
				Ū		_	· ·		_		· ·
			Subtotals	0		Subtotals	9		Subtotals	9	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	18	Overall Pi	pe Rating	18	
		Struct	ural Index	0	о	&M Index	2.0	Ove	erall Index	2.0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2900	Ovrl. Quick Rating		2900