



## Defect Listing

Pipe Segment Refere... <b>A-39_A-38</b>	City <b>Oliver Springs</b>	Street <b>Burney Dr</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Easement/R...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A-39</b>	Total Length <b>252.6</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>A-38</b>	Length surveyed <b>252.6</b>	Year Renewed	Height <b>15</b>	Width <b>15</b>	Pipe Joint... <b>N/A</b>


SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>				
OPR <b>N/A</b>	Surveyed By <b>Charlie_Gordon</b>	Direction <b>Upstream</b>	Date <b>20150903</b>	Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>No Pre-Cleaning</b>	Time <b>09:09</b>	Weather <b>Dry</b>	
Date Cleaned			End Time <b>09:17</b>	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-38									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
250.0 ft.	Water Level				10	<input type="checkbox"/>			
252.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-39									




## Image Report 4/Page

Pipe Segment Refere... <b>A-39_A-38</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Burney Dr</b>	<b>Material</b> <b>Fibreglass Reinforc...</b>		<b>Location C...</b> <b>Easement/R...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>A-39</b>	Total Length <b>252.6</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details	
<b>DS Manhole</b> <b>A-38</b>	<b>Length surveyed</b> <b>252.6</b>	Year Renewed	<b>Height</b> <b>15</b>	Width <b>15</b>	Pipe Joint...	
					<b>N/A</b>	



Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: A-38



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 250.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 252.6 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: A-39



## PACP Conditions

Pipe Segment Refere... <b>A-39_A-38</b>	City <b>Oliver Springs</b>	Street <b>Burney Dr</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Easement/R...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A-39</b>	Total Length <b>252.6</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>A-38</b>	Length surveyed <b>252.6</b>	Year Renewed	Height <b>15</b>	Width <b>15</b>	Pipe Joint... <b>N/A</b>

SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>N/A</b>		
OPR <b>N/A</b>	Surveyed By <b>Charlie Gordon</b>	Direction <b>Upstream</b>	Date <b>20150903</b>
OPRI <b>N/A</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>No Pre-Cleaning</b>	Time <b>09:09</b>
	Date Cleaned	End Time <b>09:17</b>	Weather <b>Dry</b>
			Media label
			Additional Info

Normal Defects	Structural Ratings			O & M Ratings			Combined Ratings		
	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects	1	0	0	1	0	0	1	0	0
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Code	ID	Length							
Subtotals			0	Subtotals			0	Subtotals	
SUMMARY			Pipe Rating	0	Pipe Rating			0	Overall Pipe Rating
			Structural Index	0	O&M Index			0	Overall Index
			Str. Quick Rating	0000	O&M Quick Rating			0000	Ovrl. Quick Rating