

SPR

SPRI

QSR

Pipe Segment Refere... A-5_A-4 Upstream MH A-5 DS Manhole A-4

N/A

N/A

N/A

ot Licti

		Defect Listing			5	05-341-0109	
(City	Street	Mat	erial	Location C	Sewer Use	
Oliver	Springs	Pump Station	Fibreglass	Reinforc	nforc Easement/R San		
Total	Length	Year Laid	Shape		Location Details		
23	38.9		Circ	ular			
Length	surveyed	Year Renewed	Year Renewed Height Width Pipe Joint				
23	38.9		21	21	N/A		
MPR	76	PO Number			Customer		
MPRI	2.1	4397-03			GRW		
	2.1	2.1 Work Order Purpos		Purpose			
QMR	412F	4397-02		Pre-	Rehabilitation Su	irvey	
Surve	eyed By	Direction	Date		Media label		

OPR	Surveyed By	Direction	Date		Date Medi	
76	Charlie_Gordon	Upstream	20151007			
OPRI	Certificate Number	Pre-Cleaning	Tir	ne	Weather	
2.1	U-615-07000491	No Pre-Cleaning	13:	:46	Damp	
	Date Cleaned		End	Time	Additio	nal Info
			13:	:59		

Distance	Condition	Cont. Dfct.	Values			Joint	Clock P	osition	Crede
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-4								
0.0 ft.	Water Level				20				
58.9 ft.	Deposits Attached Grease	S01			5		7	5	2
141.2 ft.	Water Level				10				
238.8 ft.	Deposits Attached Grease	F01			5		7	5	2
238.9 ft.	Alignment Left				55				4
238.9 ft.	Survey Abandoned				0				
Remarks:	Access point manhole A-5 has been lined through								



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-5_A-4	Oliver Springs	Pump Station	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A-5	238.9		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-4	238.9		21	21	N/A	











Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-5_A-4	Oliver Springs	Pump Station	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A-5	238.9		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-4	238.9		21	21	N/A	









PACP Conditions

Pipe Segme	ent Refere	C	ity	Street	Material		Location C	Sewer Use	
A-5_	A-5_A-4		Springs	Pump Station	Fibreglass	Reinforc	forc Easement/R Sai		
Upstre	am MH	Total Length		Year Laid	Shape		Location Details		
А	-5	23	8.9		Circ	Circular			
DS Ma	anhole	Length	surveyed	Year Renewed	Height	Width	Pipe Joint N/A		
Α	-4	23	8.9		21	21			
SPR	N/A	MPR	76	PO Number			Customer		
SPRI	N/A	MPRI	2.1	4397-03			GRW Purpose		
oriti	N/A		2.1	Work Order					
QSR	N/A	QMR	412F	4397-02	Pre		e-Rehabilitation Survey		
O	PR	Surve	yed By	Direction	Da	ate	Media	label	
7	6	Charlie	Gordon	Upstream	20151007				
OF	PRI	Certificat	e Number	Pre-Cleaning	Time		Weather		
2	2.1		7000491	No Pre-Cleaning	13:46 End Time		Damp		
		Date C	Cleaned	Additional Info					
					13	:59			

			Structural Ratings			O & M Ratings			Con	Combined Ratings		
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating		
			4	0	0	4	0	0	4	0	0	
			1 2	0	0	1	0	0	1 2	0	0	
			2	0	0	2	0	0	3	0	0	
			4	0	0	4	0	0	4	0	0	
			4 5	0	0	4 5	1	4	4 5	1	4	
			Э	0	0	5	0	0	5	0	0	
Contin	uous D	efects										
Code	ID	Length										
DAGS	F01	179.9	0	0	0	2	36	72	2	36	72	
			Subtotals	0		Subtotals	37		Subtotals	37		
SUMMARY		Pipe Rating Structural Index Str. Quick Rating		0 0 0000	0	pe Rating &M Index ick Rating	76 2.1 412F	Ov	ipe Rating erall Index iick Rating	76 2.1 412F		