

Defect Listing

				5					
Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A-59_	_A-58	Oliver	Springs	Green St	Concrete F	Concrete Pipe (non		Sanitary	
Upstrea	am MH	Total Length Year Laid Shape Location		Details					
A-	A-59 240.2 Circular DS Manhole Length surveyed Year Renewed Height Width Pipe		0.2			Circular			
DS Ma			Pipe Joint						
A-58		240.2			8	8	4		
SPR	5	MPR	14	PO Number		Pre-F			
0001	F	MDDI	2.5	4397-03					
SPRI	5	MPRI	3.5	Work Order					
QSR	5100	QMR	4321	4397-02				Rehabilitation Survey	
OF	PR	Surve	yed By	Direction	Di	Date		Media label	
1	9	Barry_Rogers		Upstream	2015	20150728			
OP	'RI	Certificate Number		Pre-Cleaning	Ti	Time			
3.8		U-1012-16405		Jetting	15:06		Damp		
		Date C	leaned	End	End Time		Additional Info		
		2015	0728		15	:16			

Distance	Condition	Cant Dist	Values			la int	Clock P	osition	Querda
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A-58								
0.0 ft.	Water Level				30				
21.5 ft.	Infiltration Runner				0		10		4
21.5 ft.	Infiltration Runner				0		2		4
47.9 ft.	Hole Soil Visible				0		10	2	5
55.3 ft.	Water Level Sag				10				2
122.1 ft.	Tap Break-In		6		0		9		
154.1 ft.	Roots Ball Joint				55		7		4
235.7 ft.	Tap Factory Made		6		0		3		
239.6 ft.	Water Level				5				
240.2 ft.	Access Point Manhole				0				
Remarks:	A-59	·							



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Material		Location C	Sewer Use
A-59_A-58	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary		
Upstream MH	Total Length	Year Laid	Shape		Location Details			
A-59	240.2		Circular					
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint			
A-58	240.2		8	8	4			



USMH: A DSMH: A Water Lo 0.0 ft.	-58			
Distance:	0.0 ft.	Grade:	0	
Condition:	Water Level			
Remarks:	N/A			







Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A-59_A-58	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A-59	240.2		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-58	240.2		8	8	4	



USMH: A DSMH: A Water Lo				
55.3 ft.		1		
Distance: Condition: Remarks:	55.3 ft. Water Level Sag N/A	Grade:	2	







Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Material		Location C	Sewer Use
A-59_A-58	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary		
Upstream MH	Total Length	Year Laid	Shape		Location Details			
A-59	240.2		Circular					
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint			
A-58	240.2		8	8	4			









PACP Conditions

Street City Sewer Use Pipe Segment Refere... Material Location C... A-59_A-58 **Oliver Springs** Concrete Pipe (non-... Sanitary Green St Light High... Upstream MH Total Length Year Laid Shape Location Details A-59 240.2 Circular **DS** Manhole Width Length surveyed Year Renewed Height Pipe Joint... A-58 240.2 8 8 4 PO Number Customer SPR 5 MPR 14 4397-03 GRW SPRI MPRI 3.5 5 Work Order Purpose QSR 5100 QMR 4321 4397-02 **Pre-Rehabilitation Survey** OPR Direction Media label Surveyed By Date 19 Barry_Rogers Upstream 20150728 OPRI Certificate Number Pre-Cleaning Time Weather U-1012-16405 15:06 Damp 3.8 Jetting Additional Info **Date Cleaned** End Time 20150728 15:16

			Stru	Structural Ratings			O & M Ratings			Combined Ratings		
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating		
			1	0	0	1	0	0	1	0	0	
			2	0	0	2	1	2	2	1	2	
			3	0	0	3	0	0	3	0	0	
			4	0	0	4	3	12	4	3	12	
			5	1	5	5	0	0	5	1	5	
Continu	ID	Defects										
			Subtotals	1		Subtotals	4		Subtotals	5		
SUMMARY		Struct	pe Rating ural Index ick Rating	5 5.0 5100	0	pe Rating &M Index ick Rating	14 3.5 4321	Ove	ipe Rating erall Index ick Rating	0.0		