



Defect Listing

Pipe Segment Refere... A-61_A-60	City Oliver Springs	Street Green St.	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A-61	Total Length 359	Year Laid	Shape Circular	Location Details	
DS Manhole A-60	Length surveyed 359	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Charlie Gordon	Direction Downstream	Date 20150901
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 13:50
	Date Cleaned	End Time 14:10	Weather Dry
		Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-61									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
115.1 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
182.6 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
275.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
357.4 ft.	Water Level				5	<input type="checkbox"/>			
359.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-60									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A-61_A-60	Oliver Springs	Green St.	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A-61	359		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-60	359		8	8	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-61



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 115.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 182.6 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere... A-61_A-60	City Oliver Springs	Street Green St.	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A-61	Total Length 359	Year Laid	Shape Circular		Location Details	
DS Manhole A-60	Length surveyed 359	Year Renewed	Height 8	Width 8	Pipe Joint...	4



Distance: 275.8 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 357.4 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 359.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A-60



PACP Conditions

Pipe Segment Refere... A-61_A-60	City Oliver Springs	Street Green St.	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A-61	Total Length 359	Year Laid	Shape Circular	Location Details	
DS Manhole A-60	Length surveyed 359	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Charlie Gordon	Direction Downstream	Date 20150901
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 13:50
	Date Cleaned	End Time 14:10	Weather Dry
		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									