

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A10-1_A10-1A		Oliver Springs		Walker Dr	Concrete F	Concrete Pipe (non		Sanitary
Upstream MH A10-1		Total Length 129.8		Year Laid	Sha	Shape Circular		Details
					Circ			
DS Manhole		Length surveyed		Year Renewed Height		Width	Pipe Joint	
A10	A10-1A		9.8		8	8	4	
SPR	2	MPR	N/A	PO Number		Customer		
0001		MDDI		4397-03 Work Order		GRW Purpose		
SPRI	2	MPRI	N/A					
QSR	2100	QMR	N/A	4397-02		Pre-Rehabilitation Survey		
OF	PR	Surveyed By		Direction	Da	Date		alabel
2	2	Charlie Gordon		Downstream	2015	20150817		
OF	PRI	Certificate Number		Pre-Cleaning	Tir	Time		
2		U-615-07000491		Jetting	12	12:37		
		Date C	leaned	End	End Time		Additional Info	
		2015	0817	12	12:51			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Cuada
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A10-1			•					•
0.0 ft.	Water Level				5				
50.0 ft.	Tap Factory Made		6		0		3		
63.7 ft.	Crack Spiral				0		11	12	2
97.3 ft.	Tap Factory Made		6		0		3		
126.3 ft.	Tap Factory Made		6		0		9		
126.9 ft.	Water Level				5				
129.8 ft.	Access Point Manhole				0				
Remarks:	A10-1A			•	•				•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A10-1_A10-1A	10-1_A10-1A Oliver Springs Walker Dr Concrete Pipe (non		Light High	Sanitary		
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A10-1	129.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A10-1A	129.8		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A10-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 50.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 63.7 ft. Grade: 2

Condition: Crack Spiral


Remarks: N/A





Image Report 4/Page


Pipe Segment Refere	ipe Segment Refere City		Material		Location C	Sewer Use
A10-1_A10-1A	Oliver Springs	Walker Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Upstream MH Total Length		Shape		Location Details	
A10-1	129.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A10-1A	129.8		8	8	4	



Distance: 97.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 126.3 ft. Grade: (

Condition: Tap Factory Made


Remarks: N/A



Distance: 126.9 ft. Grade: (

Condition: Water Level

Remarks: N/A



Distance: 129.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A10-1A



PACP Conditions

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use
A10-1_	A10-1A	Oliver S	Springs	Walker Dr	Concrete F	Pipe (non	Light High	Sanitary
Upstream MH		Total Length		Year Laid	Sh	Shape		n Details
A10	A10-1		9.8		Circ	ular		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	dth Pipe Joint	
A10	A10-1A		9.8		8	8	4	
SPR	2	MPR	N/A	PO Number		Customer		
SPRI	2	MPRI	N/A	4397-03		Pre-li		
SPRI		IVIFKI	IN/A	Work Order				
QSR	2100	QMR	N/A	4397-02				urvey
OF	PR	Surveyed By		Direction	Da	Date		alabel
2	2	Charlie Gordon		Downstream	2015	20150817		
OF	OPRI		e Number	Pre-Cleaning	Ti	Time		
2		U-615-07000491		Jetting	12	12:37		
		Date C	leaned	End	End Time		nal Info	
		2015	0817	12	12:51			

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	1	2	2	0	0	2	1	2
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	1		Subtotals	0		Subtotals	1	
SUMMARY	Struct	pe Rating ural Index ick Rating	2 2.0 2100	0	pe Rating &M Index ick Rating	0 0 0000	Overall Pipe Rating Overall Index Ovrl. Quick Rating		2 2.0 2100