

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A10-1	_A9-2	Oliver	Springs	Walker Dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH		Total Length		Year Laid	Sh	Shape		n Details	
A10	-1A	173	3.3		Circ	Circular			
DS Ma	inhole	Length s	surveyed	Year Renewed	Height	ght Width Pipe Joint			
A9	A9-2		3.3		8	8	4		
SPR	N/A	MPR	2	PO Number			Customer		
0001		MDDI		4397-03 Work Order		GRW			
SPRI	N/A	MPRI	2				Purpose		
QSR	N/A	QMR	2100	4397-02		Pre-	-Rehabilitation Survey		
OF	PR	Surve	ed By	Direction	Da	Date		Media label	
2	!	Charlie Gordon		Downstream	2015	20150817			
OF	RI	Certificate Number		Pre-Cleaning	Tir	Time			
2 U-615-0700		7000491	Jetting 12		12:56				
	Date Cleaned				End	End Time		Additional Info	
	20150817					13:09			

Distance	Condition	Cont. Dfct.	Values			la:n4	Clock Position		Overde
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A10-1A								
0.0 ft.	Water Level				5				
50.7 ft.	Tap Factory Made		6		0		3		
104.8 ft.	Tap Factory Made		6		0		9		
168.9 ft.	Water Level Sag				15				2
171.7 ft.	Water Level				10				
173.3 ft.	Access Point Manhole				0				
Remarks:	A9-2								•





Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
A10-1A_A9-2	Oliver Springs	Walker Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A10-1A	173.3		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-2	173.3		8	8	4	_



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A10-1A



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 50.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 104.8 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page


Pipe Segment Refere City		Street	Material		Location C	Sewer Use
A10-1A_A9-2	Oliver Springs	Walker Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A10-1A	173.3		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A9-2	173.3		8	8	4	



Distance: 168.9 ft. Grade:

Condition: Water Level Sag

Remarks: N/A



Distance: 171.7 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 173.3 ft. Grade: Condition:

Access Point Manhole

Remarks: A9-2



PACP Conditions

Pipe Segm	Pipe Segment Refere		ity	Street	Mat	Material		Sewer Use	
A10-1	A10-1A_A9-2		Springs	Walker Dr	Concrete F	Concrete Pipe (non		Sanitary	
Upstre	Upstream MH		Length	Year Laid	Sha	ape	Location	n Details	
A10	D-1A	17	3.3		Circ	ular			
DS M	anhole	Length :	surveyed	Year Renewed	Height	Width	Pipe Joint		
A:	A9-2		3.3		8	8	4		
SPR	N/A	MPR	2	PO Number	Number		Customer		
0001	N1/A	MADDI		4397-03		GRW			
SPRI	N/A	MPRI	2	Work Order			Purpose		
QSR	N/A	QMR	2100	4397-02		Pre-	e-Rehabilitation Survey		
0	PR	Surve	yed By	Direction	Date		Media label		
	2	Charlie Gordon		Downstream	20150817				
OI	OPRI		e Number	Pre-Cleaning	Time		Weather		
	2 U-615-07000491		7000491	Jetting 12		12:56			
		Date C	Cleaned	End Time		Additional Info			
		2015	0817	13:09					

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	1	2	2	1	2
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY	Struct	ipe Rating ural Index ick Rating	0 0 0000	0	pe Rating &M Index ick Rating	2 2.0 2100	Ove	ipe Rating erall Index ick Rating	2 2.0 2100