ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A11-1_A9-3		Oliver Springs		Kingston Ave	Fibreglass	Fibreglass Reinforc		Sanitary	
Up	Upstream MH		Length	Year Laid	Sh	ape	Location Details		
	A11-1	307.4			Circ	cular			
D	S Manhole	Length surveyed		Year Renewed	Height	Width	Pipe Joint		
	A9-3	307.4			8	8	N/A		
SPR	N/A	MPR	N/A	PO Number		Customer			
			-	4397-03			GRW		
SPRI	N/A	MPRI	N/A	Work Order		Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey			
	OPR	Surveyed By		Direction	Da	Date		alabel	
	N/A	Charlie Gordon		Downstream	2015	20150817			
	OPRI	Certificate Number		Pre-Cleaning	Time		Weather		
	N/A		7000491	Jetting	09:29		Dry		
		Date C	leaned		End Time		Additional Info		
		2015	0817		09	09:47			

Distance	Condition	Court Diet	Values			1-1-4	Clock Position		0
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A11-1								•
0.0 ft.	Water Level				5				
86.0 ft.	Tap Factory Made		6		0		3		
138.9 ft.	Tap Factory Made		6		0		9		
169.7 ft.	Tap Factory Made		6		0		9		
212.1 ft.	Tap Factory Made Active		6		0		3		
303.4 ft.	Water Level				5				
307.4 ft.	Access Point Manhole				0				
Remarks:	A9-3	•		•	•				•





## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A11-1_A9-3	Oliver Springs	Kingston Ave Fibreglass Reinforc		Light High	Sanitary	
Upstream MH	Jpstream MH Total Length Year Laid Shape		ape	Location Details		
A11-1	307.4		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-3	307.4		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A11-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 86.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 138.9 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





## **Image Report 4/Page**


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A11-1_A9-3	_A9-3 Oliver Springs Kingston Ave Fibreglass Reinforc		Light High	Sanitary		
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A11-1	307.4		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-3	307.4		8	8	N/A	



Distance: 169.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 212.1 ft. Grade: 0

Condition: Tap Factory Made Active

Remarks: N/A



Distance: 303.4 ft. Grade:

Condition: Water Level

Remarks: N/A



Distance: 307.4 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A9-3



## **PACP Conditions**

Pipe Segment Refere		Ci	ity	Street	Mat	erial	Location C	Sewer Use	
A11-1_A9-3		Oliver Springs		Kingston Ave	Fibreglass	Fibreglass Reinforc		Sanitary	
Upstre	Upstream MH		_ength	Year Laid	Sha	ape	Location Details		
A1	A11-1		7.4		Circ	ular			
DS Ma	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint		
L AS	A9-3		7.4		8	8	N/A		
SPR	N/A	MPR	N/A	PO Number			Customer		
SPRI	N/A	MPRI	N/A	4397-03		GRW			
SPRI	N/A	IVIPRI	IN/A	Work Order		Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre-	Pre-Rehabilitation Survey		
OF	PR	Surveyed By		Direction	Date		Media label		
N/	<b>'</b> A	Charlie Gordon		Downstream	20150817				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N.	N/A U-615-0700049		7000491	Jetting 09		09:29			
		Date C	leaned		End Time		Additional Info		
(		2015	0817		09:47				

		Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal [	Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		4			4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		0	0		0	0
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code II	D Length									
		Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		   Pi	pe Rating	0	   Pi	pe Rating	0	Overall P	pe Rating	0
		Struct	ural Index	0	0	&M Index	0	Overall Index		0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Quick Rating 0(		0000