ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A12-1_A9-4		Oliver Springs		Roane St	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH A12-1 DS Manhole		Total Length		Year Laid	Sh	Shape		Details	
		26	5.1		Circ	Circular			
		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
AS	A9-4		5.1		8	8	4		
SPR	N/A	MPR	4	PO Number			Customer		
0001	-	MPDI		4397-03		Pre-F			
SPRI	N/A	MPRI	2	Work Order					
QSR	N/A	QMR	2200	4397-02				urvey	
Ol	PR	Surve	yed By	Direction		Date Media lab		alabel	
4	4	Barry_Rogers		Upstream	20150814				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
:	2		2-16405	Jetting	14	14:38			
	Date Cleaned					End Time		Additional Info	
	20150814					14:56			

Distance	Condition	Camt Diat	Values			laint	Clock Position		Onede
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A9-4	·							
0.0 ft.	Water Level				5				
7.5 ft.	Tap Factory Made		6		0		3		
17.1 ft.	Tap Factory Made		6		0		3		
46.0 ft.	Tap Factory Made		6		0		9		
110.7 ft.	Tap Factory Made		6		0		9		
123.2 ft.	Deposits Attached Grease				0		8	9	2
139.3 ft.	Tap Factory Made		6		0		9		
153.6 ft.	Deposits Attached Grease				0		8	9	2
Remarks:	this is a continious defect			•					•
156.3 ft.	Tap Factory Made Capped		6		0		3		
180.4 ft.	Tap Factory Made		6		0		3		
262.6 ft.	Water Level				5				
265.1 ft.	Access Point Manhole				0				
Remarks:	A12-1			•	•				•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A12-1_A9-4	Oliver Springs	Roane St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A12-1	265.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-4	265.1		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A9-4



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 7.5 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 17.1 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City Street Mate		erial	Location C	Sewer Use	
A12-1_A9-4	Oliver Springs	Roane St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A12-1	265.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-4	265.1		8	8	4	



Distance: 46.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 110.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 123.2 ft. Grade: 2
Condition: Deposits Attached Grease

Remarks: N/A



Distance: 139.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A12-1_A9-4	Oliver Springs	Roane St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A12-1	265.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-4	265.1		8	8	4	



Distance: 153.6 ft. Grade: Condition: Deposits Attached Grease Remarks: this is a continious defect



Distance: 156.3 ft. Grade: Condition: Tap Factory Made Capped

Remarks: N/A



Distance: 180.4 ft. Grade: 0 Tap Factory Made

Remarks: N/A

Condition:



Distance: 262.6 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A12-1_A9-4	Oliver Springs	Roane St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	n Details
A12-1	265.1		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A9-4	265.1		8	8	4	



Distance: 265.1 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A12-1



PACP Conditions

Pipe Segment Refere Ci		ity	Street	Mat	Material		Sewer Use	
A12-1_A9-4 Oliver Springs		Springs	Roane St	Concrete F	Pipe (non	Light High	Sanitary	
Upstream MH		Total I	Length	Year Laid	Sh	ape	Location	n Details
A12-1		265.1			Circ	cular		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint	
A9	A9-4		5.1		8	8	4	
SPR	N/A	MPR	4	PO Number		Pre-l		
SPRI	N/A	MPRI	2	4397-03				
SPRI	N/A	IVIPRI		Work Order				
QSR	N/A	QMR	2200	4397-02				urvey
OF	PR	Surve	yed By	Direction	Da	Date		alabel
4	4	Barry_	Rogers	Upstream	2015	0814		
OF	PRI	Certificate Number		Pre-Cleaning	Ti	Time		
2		U-1012-16405		Jetting	14	14:38		
	Date Cleaned					End Time		nal Info
		2015	0814	14	14:56			

	Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	2	4	2	2	4
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length	-								
	Subtotals	0		Subtotals	2		Subtotals	2	
SUMMARY	Struct	pe Rating ural Index ick Rating	0	Pipe Rating 4 O&M Index 2.0 O&M Quick Rating 2200			Overall Pipe Rating Overall Index Ovrl. Quick Rating		4 2.0 2200