



## Defect Listing

Pipe Segment Refere... <b>A14-1_A9-1</b>	City <b>Oliver Springs</b>	Street <b>Central Ave</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Parking Lo...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A14-1</b>	Total Length <b>330.8</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>A9-1</b>	Length surveyed <b>330.8</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>

SPR <b>N/A</b>	MPR <b>8</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>2.7</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>4122</b>		
OPR <b>8</b>	Surveyed By <b>Charlie Gordon</b>	Direction <b>Downstream</b>	Date <b>20150817</b>
OPRI <b>2.7</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>Jetting</b>	Time <b>14:53</b>
	Date Cleaned <b>20150817</b>	End Time <b>15:13</b>	Weather <b>Light Rain</b>
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A14-1									
0.0 ft.	Water Level				10	<input type="checkbox"/>			
25.2 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
59.8 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
230.8 ft.	Tap Factory Made Active		4		0	<input type="checkbox"/>	1		
230.8 ft.	Infiltration Runner				0	<input type="checkbox"/>	1		4
243.6 ft.	Water Level Sag				10	<input type="checkbox"/>			2
276.3 ft.	Water Level Sag				15	<input type="checkbox"/>			2
327.3 ft.	Water Level				5	<input type="checkbox"/>			
330.8 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A9-1									



## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A14-1_A9-1	Oliver Springs	Central Ave	Fibreglass Reinforc...	Parking Lo...	Sanitary
Upstream MH A14-1	Total Length 330.8	Year Laid	Shape Circular	Location Details	
DS Manhole A9-1	Length surveyed 330.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: A14-1



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 25.2 ft. Grade: 0  
Condition: Tap Factory Made Active  
Remarks: N/A




Distance: 59.8 ft. Grade: 0  
Condition: Tap Factory Made Active  
Remarks: N/A




## Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A14-1_A9-1	Oliver Springs	Central Ave	Fibreglass Reinforc...	Parking Lo...	Sanitary
Upstream MH A14-1	Total Length 330.8	Year Laid	Shape Circular	Location Details	
DS Manhole A9-1	Length surveyed 330.8	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 230.8 ft. Grade: 0  
Condition: Tap Factory Made Active  
Remarks: N/A



Distance: 230.8 ft. Grade: 4  
Condition: Infiltration Runner  
Remarks: N/A



Distance: 243.6 ft. Grade: 2  
Condition: Water Level Sag  
Remarks: N/A




Distance: 276.3 ft. Grade: 2  
Condition: Water Level Sag  
Remarks: N/A




## Image Report 4/Page


Pipe Segment Refere... <b>A14-1_A9-1</b>	City <b>Oliver Springs</b>	Street <b>Central Ave</b>	Material <b>Fibreglass Reinforc...</b>		Location C... <b>Parking Lo...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A14-1</b>	Total Length <b>330.8</b>	Year Laid	Shape <b>Circular</b>		Location Details	
DS Manhole <b>A9-1</b>	Length surveyed <b>330.8</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint...	<b>N/A</b>



Distance: 327.3 ft.      Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 330.8 ft.      Grade: 0  
Condition: Access Point Manhole  
Remarks: A9-1



Pipe Segment Refere... <b>A14-1_A9-1</b>	City <b>Oliver Springs</b>	Street <b>Central Ave</b>	Material <b>Fibreglass Reinforc...</b>		Location C... <b>Parking Lo...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A14-1</b>	Total Length <b>330.8</b>	Year Laid	Shape <b>Circular</b>		Location Details	
DS Manhole <b>A9-1</b>	Length surveyed <b>330.8</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>	
SPR <b>N/A</b>	MPR <b>8</b>	PO Number <b>4397-03</b>			Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>2.7</b>				Purpose	
QSR <b>N/A</b>	QMR <b>4122</b>	Work Order <b>4397-02</b>			Pre-Rehabilitation Survey	
OPR <b>8</b>	Surveyed By <b>Charlie Gordon</b>	Direction <b>Downstream</b>	Date <b>20150817</b>		Media label	
OPRI <b>2.7</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>Jetting</b>	Time <b>14:53</b>		Weather <b>Light Rain</b>	
Date Cleaned <b>20150817</b>			End Time <b>15:13</b>		Additional Info	

Page #: 5