ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A16-3	A16-3_A16-2		Springs	kington St	Concrete Pipe (non		Light High	Sanitary	
Upstre	am MH	Total I	_ength	Year Laid	Sh	ape	Location Detai		
A1	6-3	21	3.7		Circular				
DS M	anhole	Length s	surveyed	Year Renewed	Height	leight Width Pipe Joint			
A 1	6-2	21	3.7		8 8 4		4		
SPR	N/A	MPR	4	PO Number	PO Number		Customer		
0001	-	MDDI		4397-03 Work Order			GRW		
SPRI	N/A	MPRI	2				Purpose		
QSR	N/A	QMR	2200	4397-02		Pre-	e-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Date		Media label		
	4	Barry_	Rogers	Downstream	20150813				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2	2		2-16405	No Pre-Cleaning	14	14:34 Very Dry End Time Additi			
		Date C	leaned	End				nal Info	
					14	:54			

Distance 0.0 ft. Remarks:	O and Millian	Ocasi Dici	Values			1-1-4	Clock Po	Clock Position	
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	Position To 9	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A16-3								•
0.0 ft.	Water Level				5				
6.0 ft.	Tap Factory Made		6		0		3		
18.1 ft.	Tap Factory Made		6		0		3		
83.5 ft.	Tap Factory Made		6		0		3		
93.4 ft.	Tap Factory Made		6		0		9		
171.0 ft.	Obstacle Other				10		6		2
Remarks:	piece of wood or metal								•
212.4 ft.	Tap Factory Made Active		6		0		6		
213.6 ft.	Water Level				5				
213.6 ft.	Obstacle Built Into Structure				10		3	9	2
Remarks:	BUILT IN MORTAR	•		•					•
213.7 ft.	Access Point Manhole				0				
Remarks:	A16-2								





Image Report 4/Page

	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	A16-3_A16-2	Oliver Springs	kington St	Concrete F	Pipe (non	Light High	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location Deta	
	A16-3	213.7		Circular			
Г	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
	A16-2	213.7		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A16-3



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 6.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 18.1 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





Image Report 4/Page

	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	A16-3_A16-2	Oliver Springs	kington St	Concrete Pipe (non		Light High	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location	Details
	A16-3	213.7		Circular			
Г	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
	A16-2	213.7		8	8	4	



Distance: 83.5 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A



Distance: 93.4 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 171.0 ft. Grade: 2

Condition: Obstacle Other

Remarks: piece of wood or metal



Distance: 212.4 ft. Grade: 0

Condition: Tap Factory Made Active

Remarks: N/A





Image Report 4/Page


Pipe Segment Refere	City	Street	Mat	Material		Sewer Use
A16-3_A16-2	Oliver Springs	kington St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A16-3	213.7		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A16-2	213.7		8	8	4	



Distance: 213.6 ft. Grade:

Condition: Water Level

Remarks: N/A



Distance: 213.6 ft. Grade: 2 Condition: Obstacle Built Into Structure

Remarks: **BUILT IN MORTAR**



Distance: 213.7 ft. Grade: 0 Condition:

Access Point Manhole

Remarks: A16-2



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A16-3_	_A16-2	Oliver	Springs	kington St	Concrete F	Pipe (non	e (non Light High S	
Upstrea	am MH	Total Length		Year Laid	Sh	Shape		Details
A1	6-3	21	3.7		Circ	Circular		
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width		
A1	6-2	21	3.7		8	8		
SPR	N/A	MPR	4	PO Number				
SPRI	N/A	MPRI	2	4397-03 Work Order		GRW		
SFRI	IN/A	IVIFKI					Purpose	
QSR	N/A	QMR	2200	4397-02		Pre-	-Rehabilitation Survey	
OF	PR	Surveyed By		Direction	Da	Date		alabel
4	1	Barry_Rogers		Downstream	2015	20150813		
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
2	2		2-16405	No Pre-Cleaning		14:34		
		Date C	leaned	End	End Time		nal Info	
					14	:54		

	Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	2	4	2	2	4
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	2		Subtotals	2	
SUMMARY	Pipe Rating 0 Structural Index 0			Pipe Rating O&M Index O&M Quick Rating		4 2.0 2200	Overall Pipe Rating Overall Index Ovrl. Quick Rating		4 2.0 2200