ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A19-1_A8-6 Upstream MH A19-1 DS Manhole A8-6		Oliver Springs Total Length 160.9 Length surveyed 160.9		Roane St	Fibreglass	Fibreglass Reinforc		Sanitary
				Year Laid	Sh	ape	Location	Details
					Circ	Circular		
				Year Renewed	Height	Width	Pipe Joint	
					8	8	N/A	
SPR	3	MPR	10	PO Number		PO Number Custom		
				4397-03				
SPRI	3	MPRI	2	Work Order				
QSR	3100	QMR	2500	4397-02		Pre-Rehabilitation Survey		
OI	PR	Surve	yed By	Direction	D	Date		alabel
1	3	Barry_Rogers		Downstream	2015	20150813		
OF	PRI	Certificate Number		Pre-Cleaning	Ti	Time		
2.2		U-1012-16405		Jetting	10	10:20		
		Cleaned		End Time		Additio	Additional Info	
		2015	0813		10	:31		

Distance	Condition	Cant Diat	Values			1 - 1 - 1	Clock Position		0
Distalice	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A19-1			•			•		•
0.0 ft.	Water Level				5				
49.0 ft.	Deposits Attached Grease				0		8		2
49.0 ft.	Deposits Attached Grease				0		4		2
49.3 ft.	Deposits Attached Grease				5		7		2
65.5 ft.	Tap Factory Made		6		0		9		
67.4 ft.	Lining Failure Wrinkled						7	8	3
68.1 ft.	Water Level Sag				5				2
109.0 ft.	Water Level Sag				10				2
157.8 ft.	Water Level				20				
160.9 ft.	Access Point Manhole				0				
Remarks:	A8-6				•		•		•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A19-1_A8-6	Oliver Springs	Roane St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A19-1	160.9		Circular			
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A8-6	160.9		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A19-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance:49.0 ft.Grade:Condition:Deposits Attached Grease

Remarks: N/A



Distance: 49.0 ft. Grade: 2

Condition: Deposits Attached Grease

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A19-1_A8-6	Oliver Springs	Roane St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A19-1	160.9		Circular			
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A8-6	160.9		8	8	N/A	ر ا



Distance: 49.3 ft. **Grade**: 2 **Condition**: Deposits Attached Grease

Remarks: N/A



Distance: 65.5 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 67.4 ft. Grade: 3

Condition: Lining Failure Wrinkled

Remarks: N/A



Distance: 68.1 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page


Pipe Segment Refere City		Street	Material		Location C	Sewer Use
A19-1_A8-6	Oliver Springs	Roane St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A19-1	9-1 160.9 Circular		ular			
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A8-6	160.9		8	8	N/A	



Distance: 109.0 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



157.8 ft. Distance: Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 160.9 ft. Grade: 0 Condition:

Access Point Manhole

Remarks: A8-6



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A19-1_A8-6 Upstream MH A19-1 DS Manhole A8-6		Oliver Springs Total Length 160.9 Length surveyed 160.9		Roane St	Fibreglass	Fibreglass Reinforc		Sanitary
				Year Laid	Sh	ape	Location	Details
					Circ	Circular		
				Year Renewed	Height	Width	Pipe Joint	
					8	8	N/A	
SPR	3	MPR	10	PO Number		PO Number Custom		
				4397-03				
SPRI	3	MPRI	2	Work Order				
QSR	3100	QMR	2500	4397-02		Pre-Rehabilitation Survey		
OI	PR	Surve	yed By	Direction	D	Date		alabel
1	3	Barry_Rogers		Downstream	2015	20150813		
OF	PRI	Certificate Number		Pre-Cleaning	Ti	Time		
2.2		U-1012-16405		Jetting	10	10:20		
		Cleaned		End Time		Additio	Additional Info	
		2015	0813		10	:31		

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	4			4			4		•
	1	0	0	1	0	0	1	0	0
	2	0	0	2	5	10	2	5	10
	3	1	3	3	0	0	3	1	3
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects									
Code ID Length									
	Subtotals	1		Subtotals	5		Subtotals	6	
SUMMARY	Pipe Rating		3	Pipe Rating		10	Overall Pipe Rating		13
	Struct	ural Index	3.0	0	&M Index	2.0	Ove	erall Index	2.2
	Str. Qu	ick Rating	3100	O&M Qui	ick Rating	2500	Ovrl. Qu	ick Rating	3125