ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A2-3_A2-2		Oliver Springs		Kingtin St	Fibreglass	Fibreglass Reinforc		Sanitary
Upstream MH A2-3 DS Manhole		Total Length		Year Laid	Sh	ape	Location	Details
		31	0.7		Circ	Circular		
		Length surveyed		Year Renewed	Height	Width	Pipe Joint	
A2	A2-2		0.7		8	8	N/A	
SPR	N/A	MPR	6	PO Number		Pre-		
ODDI		MDDI		4397-03				
SPRI	N/A	MPRI	2	Work Order				
QSR	N/A	QMR	2300	4397-02				urvey
OF	PR	Surve	yed By	Direction	Di	Date		alabel
6	6	Charlie Gordon		Downstream	2015	20150818		
OP	PRI	Certificate Number		Pre-Cleaning	Ti	Time		
2		U-615-07000491		Jetting	10	10:30		
		Date C	End Time		Additional Info			
	20150818					10:54		

Distance	Condition	Court Direct	Values			laint	Clock Position		Oneda
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A2-3				•				
0.0 ft.	Water Level				5				
32.4 ft.	Tap Factory Made		6		0		3		
35.8 ft.	Tap Factory Made		6		0		10		
82.4 ft.	Tap Factory Made Active		6		0		3		
150.1 ft.	Tap Factory Made Active		6		0		3		
185.4 ft.	Water Level Sag				5				2
210.4 ft.	Water Level Sag				5				2
251.6 ft.	Tap Factory Made		6		0		3		
251.6 ft.	Deposits Attached Ragging				5		5		2
293.1 ft.	Tap Factory Made		6		0		3		
308.3 ft.	Water Level				5				
310.7 ft.	Access Point Manhole				0				
Remarks:	A2-2								





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A2-3_A2-2	Oliver Springs	Kingtin St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A2-3	310.7		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A2-2	310.7		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A2-3



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 32.4 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 35.8 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A






Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A2-3_A2-2	Oliver Springs	Kingtin St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A2-3	310.7		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A2-2	310.7		8	8	N/A	ر ا



Distance: 82.4 ft. **Grade**: 0 **Condition**: Tap Factory Made Active

Remarks: N/A



Distance: 150.1 ft. **Grade**: 0 **Condition**: Tap Factory Made Active

Remarks: N/A



Distance: 185.4 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 210.4 ft. Grade: 2

Condition: Water Level Sag


Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A2-3_A2-2	Oliver Springs	Kingtin St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A2-3	310.7		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A2-2	310.7		8	8	N/A	



Distance: 251.6 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 251.6 ft. **Grade:** 2 **Condition:** Deposits Attached Ragging

Remarks: N/A



Distance: 293.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 308.3 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A2-3_A2-2	Oliver Springs	Kingtin St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A2-3	310.7		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A2-2	310.7		8	8	N/A	



Distance: 310.7 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A2-2



PACP Conditions

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A2-3_A2-2		Oliver Springs		Kingtin St	Fibreglass Reinforc		Light High	Sanitary	
Upst	Upstream MH		Length	Year Laid	Shape		Location Details		
	A2-3		0.7		Circ	ular			
DS	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint		
	A2-2		0.7		8	8	N/A		
SPR	N/A	MPR	6	PO Number			Customer		
2001				4397-03			GRW		
SPRI	N/A	MPRI	2	Work Order	Pre-l		Purpose -Rehabilitation Survey		
QSR	N/A	QMR	2300	4397-02					
	OPR	Surve	yed By	Direction	Date		Media label		
	6	Charlie	Gordon	Downstream	20150818				
(OPRI	Certificate Number		Pre-Cleaning	Time		Weather		
	2 U-61		7000491	Jetting	10:30		Damp		
	Date Cleaned					Time	Additional Info		
	20150818					:54			

	Stru	ctural Rat	ings	0	& M Ratin	gs	Com	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	3	6	2	3	6
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects Code ID Length									
	Subtotals	0		Subtotals	3		Subtotals	3	
SUMMARY	Struct	ipe Rating ural Index ick Rating	0 0 0000			pe Rating erall Index ick Rating	6 2.0 2300		