505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A20-7_A20-6		Oliver Springs		Hwy 62 Exit Ramp	PolyVinyl Chloride		Main Highw	Sanitary	
Upstream MH A20-7 DS Manhole		Total Length 270.8 Length surveyed		Year Laid	Shape Circular		Location Details		
				Year Renewed	Height Width		Pipe Joint		
A2	0-6	27	0.8		8	8	8 13		
SPR	N/A	MPR	N/A	PO Number 4397-03			Customer		
-						GRW			
SPRI	N/A	MPRI	N/A	Work Order			Purpose		
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey			
OF	PR	Surveyed By		Direction	Date		Media label		
N/	/A	Barry_Rogers		Downstream	20150806				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N/A		U-1012-16405		Jetting	13:34		Heavy Rain		
		Date C	leaned		End Time Ad		Addition	nal Info	
		2015	0806	13	:41				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A20-7								
0.0 ft.	Water Level				5				
267.5 ft.	Water Level				10				
270.8 ft.	Access Point Manhole				0				
Remarks:	A20-6								





Image Report 4/Page


Pipe Segment Refere	City	Street	eet Materia		Location C	Sewer Use
A20-7_A20-6	Oliver Springs	Hwy 62 Exit Ramp	PolyVinyl Chloride		Main Highw	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A20-7	270.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A20-6	270.8		8	8	13	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A20-7



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 267.5 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 270.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A20-6



PACP Conditions

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A20-7_A20-6		Oliver Springs		Hwy 62 Exit Ramp	PolyViny	l Chloride	Main Highw	Sanitary	
Upstream MH		Total Length		Year Laid	Shape		Location Details		
A20-7		270.8		Circ		ular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint			
A2	0-6	270.8			8	8	13		
SPR	N/A	MPR	N/A	PO Number		Customer			
SPRI	N/A	MPRI	N/A	4397-03			GRW		
SPRI	N/A	IVIPRI	N/A	Work Order			Purpose		
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Surv		urvey	
OF	PR	Surveyed By		Direction	Da	ate Media lab		label	
N	/ A	Barry_Rogers		Downstream	20150806				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
N	N/A		2-16405	Jetting	13:	:34	Heavy Rain		
		Date C	Cleaned	•	End Time Addition		nal Info		
		2015	60806	13:41					

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			4			4			4		
			2	0	0	2	0	0	2	0	0
				0	0		0	0		0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu	ous C	Defects									
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SIII	ММΔ	RY	Pi	pe Rating	0	Pipe Rating		0	Overall P	Pipe Rating (
SUMMARY		Struct	ural Index	0	O&M Index		0	Overall Index		0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000