



Defect Listing

Pipe Segment Refere... A20-8_A20-7	City Oliver Springs	Street Hwy62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A20-8	Total Length 212.2	Year Laid	Shape Circular	Location Details	
DS Manhole A20-7	Length surveyed 212.2	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A				
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150805	Media label	
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 05:54	Weather Very Dry	
Date Cleaned 20150805			End Time 06:04	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A20-8									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
29.5 ft.	Material Change				0	<input type="checkbox"/>			
Remarks: CP to PVC									
209.3 ft.	Water Level				5	<input type="checkbox"/>			
212.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A20-7									



Image Report 4/Page


Pipe Segment Refere... A20-8_A20-7	City Oliver Springs	Street Hwy62	Material Concrete Pipe (non-...		Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A20-8	Total Length 212.2	Year Laid	Shape Circular		Location Details	
DS Manhole A20-7	Length surveyed 212.2	Year Renewed	Height 8	Width 8	Pipe Joint...	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A20-8



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 29.5 ft. Grade: 0
Condition: Material Change
Remarks: CP to PVC




Distance: 209.3 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A20-8_A20-7	City Oliver Springs	Street Hwy62	Material Concrete Pipe (non-...		Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A20-8	Total Length 212.2	Year Laid	Shape Circular		Location Details	
DS Manhole A20-7	Length surveyed 212.2	Year Renewed	Height 8	Width 8	Pipe Joint...	4



Distance: 212.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A20-7



PACP Conditions

Pipe Segment Refere... A20-8_A20-7	City Oliver Springs	Street Hwy62	Material Concrete Pipe (non-...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A20-8	Total Length 212.2	Year Laid	Shape Circular	Location Details	
DS Manhole A20-7	Length surveyed 212.2	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150805	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 05:54		Weather Very Dry	
Date Cleaned 20150805			End Time 06:04		Additional Info

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									