505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A20-9_	A20-8	Oliver S	Springs	Hwy 62	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH Total Length		_ength	Year Laid	Sh	ape	Location Details			
A20-9		288.7			Circ	cular			
DS Ma	nhole	Length s	surveyed	Year Renewed	Year Renewed Height Width Pipe Joint		Pipe Joint		
A20	0-8	288.7			8	8	4		
SPR	N/A	MPR	N/A	PO Number		Customer GRW			
SPRI	N/A	MPRI	N/A	4397-03					
OI 101	19/7	IVII IXI	11//	Work Order					
QSR	N/A	QMR	N/A	4397-02		Pre-	re-Rehabilitation Survey		
OF	PR	Survey	yed By	Direction	Di	Date		label	
N/	Ά	Barry_Rogers		Downstream	2015	20150805			
OP	OPRI		e Number	Pre-Cleaning	Time		Weather		
N/A U-1012-16405		Jetting	04	04:52					
	Date Cleaned					End Time		nal Info	
		2015	0805	05	05:09				


Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A20-9								
0.0 ft.	Water Level				5				
8.0 ft.	Tap Factory Made		6		0		3		
283.3 ft.	Water Level				5				
288.7 ft.	Access Point Manhole				0				
Remarks:	A20-8								





Image Report 4/Page

Pipe Segment Refere	Pipe Segment Refere City		Material		Location C	Sewer Use
A20-9_A20-8	Oliver Springs	Hwy 62	Concrete Pipe (non		Main Highw	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A20-9	288.7		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A20-8	288.7		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A20-9



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 8.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 283.3 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	Pipe Segment Refere City		Material		Location C	Sewer Use
A20-9_A20-8	Oliver Springs	Hwy 62	Concrete Pipe (non		Main Highw	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A20-9	288.7		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A20-8	288.7		8	8	4	



Distance: 288.7 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A20-8



PACP Conditions

Pipe Segme	ent Refere	Ci	ity	Street	Mat	erial	Location C	Sewer Use
A20-9	A20-9_A20-8		Springs	Hwy 62	Concrete P	ipe (non	Main Highw	Sanitary
Upstre	Upstream MH		_ength	Year Laid	Shape		Location Details	
A2	A20-9		8.7		Circular			
DS Ma	anhole	Length s	surveyed	Year Renewed	ewed Height Width Pipe Joint		Pipe Joint	
A2	A20-8		8.7		8	8	4	
SPR	N/A	MPR	N/A	PO Number			Customer GRW Purpose	
SPRI	N/A	MPRI	N/A	4397-03				
0.70	-			Work Order				
QSR	N/A	QMR	N/A	4397-02	Pre-		Rehabilitation Survey	
OF	PR	Surveyed By		Direction	Date		Media label	
N/	/A	Barry_Rogers		Downstream	20150805			
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
N.	N/A		2-16405	Jetting	04:52		Very Dry	
		Date C	leaned	End Time		Additional Info		
(2015	0805	05:09				

	Structural Ratings			0	& M Ratin	gs	Con	Combined Ratings		
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
	4			4			4	•	•	
	2	0	0	2	0	0	2	0	0	
		0	0	3	0	0	3	0	0	
	3	0	0		0	0		0	0	
	5	0	0	4	0	0	4	0	0	
) 5	0	0	5	0	0	5	0	0	
Continuous Defects										
Code ID Length										
	1									
	1									
	Subtotals	0		Subtotals	0		Subtotals	0		
SUMMARY	Pi	ipe Rating	0	Pi	pe Rating	0	Overall Pi	pe Rating	0	
SUIVIIVIAR		Structural Index			&M Index	0	Overall In		0	
	Str. Qu	Str. Quick Rating		O&M Quick Rating		0000	Ovrl. Quick Rating 0		0000	