

Defect Listing

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A24-1_A20-3		Oliver Springs		Main St	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH Total Length		Length	Year Laid	Sha	Shape		Details		
A24-1		50.5			Circ	ular			
DS Ma	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint		
A20-3		50.5			8	8	4		
SPR	N/A	MPR	2	PO Number			Customer		
			_	4397-03		GRW			
SPRI	N/A	MPRI	2	Work Order			Purpose		
QSR	N/A	QMR	2100	4397-02		Pre-Rehabilitation Survey			
Ol	PR	Surveyed By		Direction	Date		Media label		
2	2	Barry_Rogers		Downstream	20150811				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2		U-1012-16405		Jetting	10:07		Dry		
		Date C	leaned		End Time		Addition	Additional Info	
		2015	0811	10:12					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade	
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade	
0.0 ft.	Access Point Manhole				0					
Remarks:	A24-1									
0.0 ft.	Water Level				5					
0.2 ft.	Deposits Settled Other				10		4	7	2	
Remarks:	s: ball of toilet paper an other debris									
48.7 ft.	Water Level				5					
50.5 ft.	Access Point Manhole				0					
Remarks:	A20-3	•							•	





Image Report 4/Page

Pipe Segment Refere	City	Street Material		Location C	Sewer Use	
A24-1_A20-3	Oliver Springs	Main St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A24-1	50.5		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A20-3	50.5		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A24-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 0.2 ft. Grade: 2
Condition: Deposits Settled Other

Remarks: ball of toilet paper an other debris



Distance: 48.7 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street Material		Location C	Sewer Use	
A24-1_A20-3	Oliver Springs	Main St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A24-1	50.5		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A20-3	50.5		8	8	4	



Distance: 50.5 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A20-3



PACP Conditions

Pipe Segment Refere		С	ity	Street	Mat	erial	Location C	Sewer Use	
A24-1_A20-3 OI		Oliver	Springs	Main St	Concrete F	Pipe (non	Light High	Sanitary	
Upstream MH A24-1		Total Length 50.5		Year Laid	Sh	Shape Circular		Details	
					Circ				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A2	A20-3		0.5		8	8	4		
SPR	N/A	MPR	2	PO Number		Customer			
SPRI	N/A	MPRI	2	4397-03		Pre-F			
SFRI	IN/A	IVIFKI		Work Order					
QSR	N/A	QMR	2100	4397-02				-Rehabilitation Survey	
OF	PR	Surveyed By		Direction	D	Date		Media label	
2	2	Barry_Rogers		Downstream	2015	20150811			
OF	OPRI		e Number	Pre-Cleaning	Ti	Time			
2	2 U-101		2-16405	Jetting	10	10:07			
		Date C	Cleaned		End Time		Additional Info		
		2015	0811	10	10:12				

	Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1			4			4		
	1 2	0	0	2	0	0	2	0	0
	3	0	0	3	1	2	3	1	2
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
) 3	0	0) 5	0	0) 5	0	0
Continuous Defects									
Code ID Lengt	h								
	_								
	_								
	Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY	Р	ipe Rating	0	Pi	ipe Rating	2	Overall P	ipe Rating	2
O I I I I I I I I I I I I I I I I I I I	Struct	ural Index	0	O&M Index		2.0	Overall Index		2.0
	Str. Qu	ick Rating	0000	O&M Quick Rating		2100	Ovrl. Quick Rating 210		2100