



Defect Listing

Pipe Segment Refere... A24-1A_A24-1	City Oliver Springs	Street Morgen St	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A24-1A	Total Length 303.5	Year Laid	Shape Circular	Location Details	
DS Manhole A24-1	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Barry Rogers	Direction Downstream	Date 20150803
OPRI N/A	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 09:09
	Date Cleaned 20150803	End Time 09:28	Weather Dry
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A24-1A									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
52.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
172.6 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
241.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
244.9 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
266.8 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
300.1 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	6		
303.5 ft.	Water Level				5	<input type="checkbox"/>			
303.5 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A24-1									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A24-1A_A24-1	Oliver Springs	Morgen St	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH A24-1A	Total Length 303.5	Year Laid	Shape Circular	Location Details	
DS Manhole A24-1	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A24-1A



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 52.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 172.6 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A24-1A_A24-1	Oliver Springs	Morgen St	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH A24-1A	Total Length 303.5	Year Laid	Shape Circular	Location Details	
DS Manhole A24-1	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 241.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 244.9 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 266.8 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 300.1 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A24-1A_A24-1	Oliver Springs	Morgen St	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A24-1A	303.5		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A24-1	303.5		8	8	4



Distance: 303.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 303.5 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A24-1



PACP Conditions

Pipe Segment Refere... A24-1A_A24-1	City Oliver Springs	Street Morgen St	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A24-1A	Total Length 303.5	Year Laid	Shape Circular	Location Details	
DS Manhole A24-1	Length surveyed 303.5	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream		Date 20150803	
OPR N/A	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI N/A	Certificate Number U-1012-16405	Time 09:09		Weather Dry	
Date Cleaned 20150803			End Time 09:28		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									