

Defect Listing

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A24-4	A24-4_A24-3		Springs	Morgen ST	Concrete Pipe (non		Light High	Sanitary	
Upstream MH		Total Length		Year Laid	Sh	ape	Location Details		
A24-4		149.8			Circ	ular			
DS Ma	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint		
A24-3		149.8			8	8	4		
SPR	N/A	MPR	N/A	PO Number	PO Number		Customer		
0001				4397-03	GRW				
SPRI	N/A	MPRI	N/A	Work Order		Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey			
O	PR	Surveyed By		Direction	Date		Media label		
N	/A	Barry_Rogers		Downstream	20150803				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A		U-1012-16405		Jetting	06:56		Damp		
		Date C	leaned	End Time		Additional Info			
		2015	0803	07:18					

Distance	Condition	Cont. Dfct.	Values			laint	Clock Position		Cuada
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A24-4								
0.0 ft.	Water Level				5				
4.5 ft.	Tap Factory Made		6		0		3		
43.7 ft.	Tap Factory Made		6		0		9		
147.7 ft.	Water Level				5				
149.8 ft.	Access Point Manhole				0				
Remarks:	A24-3			•					•





Image Report 4/Page


Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A24-4_A24-3	Oliver Springs	Morgen ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A24-4	149.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A24-3	149.8		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A24-4



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 4.5 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 43.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A24-4_A24-3	Oliver Springs	Morgen ST	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A24-4	149.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A24-3	149.8		8	8	4	



Distance: 147.7 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 149.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A24-3



PACP Conditions

Pipe Segme	Pipe Segment Refere		ity	Street	Mat	Material		Sewer Use
A24-4_A24-3		Oliver Springs		Morgen ST	Concrete F	Concrete Pipe (non		Sanitary
Upstrea	Upstream MH		_ength	Year Laid	Sh	Shape		n Details
A2	A24-4		9.8		Circ	ular		
DS Ma	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint	
A2	A24-3		9.8		8	8	4	
SPR	N/A	MPR	N/A	PO Number		Customer GRW		
SPRI	N/A	MPRI	N/A	4397-03				
OI III		IVII TXI	-	Work Order				
QSR	N/A	QMR	N/A	4397-02		Pre-l		Survey
OF	PR	Surveyed By		Direction	Da	Date		a label
N/	N/A		Rogers	Downstream	2015	20150803		
OF	OPRI		e Number	Pre-Cleaning	Time		Weather	
N/	N/A		2-16405	Jetting	06:56		Damp	
		Date C	leaned	End Time		Additional Info		
		2015	0803	07	07:18			

	Structural Ratings			0	& M Ratin	gs	Combined Ratings		
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	4			4			4		•
	2	0	0	2	0	0	2	0	0
		0	0	3	0	0	3	0	0
	3	0	0		0	0		0	0
	5	0	0	4	0	0	4	0	0
) 5	0	0	5	0	0	5	0	0
Continuous Defects									
Code ID Length									
	1								
	-								
	Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY	Pi	ipe Rating	0	Pi	pe Rating	0	Overall Pi	pe Rating	0
SUIVIIVIAR		ural Index	0		&M Index	0		erall Index	0
	Str. Qu	ick Rating		O&M Quick Rating		0000	Ovrl. Quick Rating (0000