



Defect Listing

Pipe Segment Refere... A25-2_A25-1	City Oliver Springs	Street Spring St	Material Fibreglass Reinforc...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-2	Total Length 239.5	Year Laid	Shape Circular	Location Details	
DS Manhole A25-1	Length surveyed 239.5	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR 2	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2100		
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150803
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:22
	Date Cleaned 20150803	End Time 14:36	Weather Dry
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A25-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
9.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
19.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
140.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
183.1 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
225.1 ft.	Water Level Sag				10	<input type="checkbox"/>			2
235.5 ft.	Water Level				5	<input type="checkbox"/>			
239.5 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A25-1									




Image Report 4/Page


Pipe Segment Refere... A25-2_A25-1	City Oliver Springs	Street Spring St	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-2	Total Length 239.5	Year Laid	Shape Circular		Location Details	
DS Manhole A25-1	Length surveyed 239.5	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A25-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 9.2 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 19.0 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A25-2_A25-1	Oliver Springs	Spring St	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A25-2	239.5		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A25-1	239.5		8	8	N/A



Distance: 140.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 183.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 225.1 ft. Grade: 2
Condition: Water Level Sag
Remarks: N/A




Distance: 235.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A25-2_A25-1	Oliver Springs	Spring St	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A25-2	239.5		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A25-1	239.5		8	8	N/A



Distance: 239.5 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A25-1



Pipe Segment Refere... A25-2_A25-1	City Oliver Springs	Street Spring St	Material Fibreglass Reinforc...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-2	Total Length 239.5	Year Laid	Shape Circular		Location Details	
DS Manhole A25-1	Length surveyed 239.5	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose		
QSR N/A	QMR 2100			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Downstream	Date 20150803		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 14:22		Weather Dry	
Date Cleaned 20150803			End Time 14:36		Additional Info	

Page #: 5