



Defect Listing

Pipe Segment Refere... A25-3_A25-2	City Oliver Springs	Street Spring St	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-3	Total Length 281.8	Year Laid	Shape Circular	Location Details	
DS Manhole A25-2	Length surveyed 281.8	Year Renewed	Height 8	Width 8	Pipe Joint... 4


SPR 3	MPR N/A	PO Number 4397-03	Customer GRW
SPRI 3	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR 3100	QMR N/A		
OPR 3	Surveyed By Barry Rogers	Direction Downstream	Date 20150803
OPRI 3	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 13:54
	Date Cleaned 20150803	End Time 14:10	Weather Dry
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A25-3									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
31.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
80.1 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
107.9 ft.	Hole				0	<input checked="" type="checkbox"/>	9		3
109.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
196.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
238.3 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
279.5 ft.	Water Level				5	<input type="checkbox"/>			
281.8 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A25-2									




Image Report 4/Page


Pipe Segment Refere... A25-3_A25-2	City Oliver Springs	Street Spring St	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-3	Total Length 281.8	Year Laid	Shape Circular		Location Details	
DS Manhole A25-2	Length surveyed 281.8	Year Renewed	Height 8	Width 8	Pipe Joint... 4	




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A25-3



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 31.4 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 80.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A25-3_A25-2	Oliver Springs	Spring St	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH A25-3	Total Length 281.8	Year Laid	Shape Circular	Location Details	
DS Manhole A25-2	Length surveyed 281.8	Year Renewed	Height 8	Width 8	Pipe Joint... 4




Distance: 107.9 ft. Grade: 3
Condition: Hole
Remarks: N/A



Distance: 109.2 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Distance: 196.7 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 238.3 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A25-3_A25-2	City Oliver Springs	Street Spring St	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-3	Total Length 281.8	Year Laid	Shape Circular		Location Details	
DS Manhole A25-2	Length surveyed 281.8	Year Renewed	Height 8	Width 8	Pipe Joint...	4



Distance: 279.5 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 281.8 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A25-2



PACP Conditions

Pipe Segment Refere... A25-3_A25-2	City Oliver Springs	Street Spring St	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A25-3	Total Length 281.8	Year Laid	Shape Circular	Location Details	
DS Manhole A25-2	Length surveyed 281.8	Year Renewed	Height 8	Width 8	Pipe Joint... 4
SPR 3	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI 3	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 3100	QMR N/A	Direction Downstream		Date 20150803	
OPR 3	Surveyed By Barry Rogers	Pre-Cleaning Jetting		Media label	
OPRI 3	Certificate Number U-1012-16405	Time 13:54		Weather Dry	
Date Cleaned 20150803			End Time 14:10		Additional Info

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	1	3	3	0	0	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continuous Defects											
Code	ID	Length									