

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A25-5_A25-4		Oliver Springs		Spring St	Fibreglass Reinforc		Light High	Sanitary	
Upstream MH A25-5		Total Length 201.7		Year Laid	Shape Circular		Location Details		
DS Ma	DS Manhole A25-4		surveyed	Year Renewed	Height	Width	Pipe Joint <b>N/A</b>		
A2			1.7		8	8			
SPR	N/A	MPR	N/A	PO Number			Customer GRW Purpose		
2001				4397-03					
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02			urvey		
O	PR	Surveyed By		Direction	Date		Media label		
N	/A	Barry_Rogers		Downstream	20150803				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N	N/A		2-16405	Jetting	10:02		Dry		
		Date C	leaned	End Time		Additional Info			
		2015	0803	10:14					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A25-5								
0.0 ft.	Water Level				10				
79.0 ft.	Tap Factory Made		6		0		3		
121.2 ft.	Tap Factory Made		6		0		9		
143.7 ft.	Tap Factory Made		6		0		3		
197.9 ft.	Water Level				5				
201.7 ft.	Access Point Manhole				0				
Remarks:	A25-4								





## Image Report 4/Page


Pipe Segment Refere	Pipe Segment Refere City		Material		Location C	Sewer Use
A25-5_A25-4	Oliver Springs	Spring St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A25-5	201.7		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A25-4	201.7		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A25-5



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 79.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 121.2 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





## **Image Report 4/Page**

Pipe Segment Refere	Pipe Segment Refere City		Material		Location C	Sewer Use
A25-5_A25-4	Oliver Springs	Spring St	Fibreglass Reinforc		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A25-5	201.7		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A25-4	201.7		8	8	N/A	



Distance: 143.7 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 197.9 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 201.7 ft. Grade: 0
Condition: Access Point Manhole

Remarks: A25-4



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use
A25-5_A25-4		Oliver Springs		Spring St	Fibreglass	Fibreglass Reinforc		Sanitary
Upstream MH <b>A25-5</b>		Total Length 201.7		Year Laid	Sh	Shape Circular		Details
					Circ			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint	
A2	A25-4		1.7		8	8	N/A	
SPR	N/A	MPR	N/A	PO Number		Customer		
SPRI	N/A	MPRI	N/A	4397-03		Pre-		
SFRI	IN/A	IVIFKI	IN/A	Work Order				
QSR	N/A	QMR	N/A	4397-02				urvey
OF	PR	Surveyed By		Direction	Da	Date		alabel
N/	/A	Barry_Rogers		Downstream	2015	20150803		
OP	PRI	Certificate Number		Pre-Cleaning	Ti	Time		
N/A U		U-1012	2-16405	Jetting	10	10:02		
		Date C	leaned	End	End Time		nal Info	
		2015	0803	10	10:14			

	Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	ings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Continuous Defects  Code ID Length									
	Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		pe Rating ural Index	0	Pipe Rating O&M Index		0	Overall Pipe Rating Overall Index		0
		ick Rating	0000	1	ick Rating	0000	1	ick Rating	0000