

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A26-1_	_A25-3	-3 Oliver Springs Pine st Concrete		Concrete F	Pipe (non	Light High	Sanitary		
Upstream MH		Total Length		Year Laid	Shape		Location Details		
A2	A26-1		4.1		Circ	ular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A2	A25-3		4.1		8	8	4		
SPR	N/A	MPR	N/A	PO Number	Number		Customer		
0001	NI/A	MDDI	NI/A	4397-03	GRW Purpose				
SPRI	N/A	MPRI	N/A	Work Order					
QSR	N/A	QMR	N/A	4397-02	Pre-Rehabilitation Survey				
OF	PR	Survey	ed By	Direction	Date		Media label		
N/	/A	Barry_Rogers		Downstream	20150803				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A U-1012-16405		Jetting	10:51		Dry				
		Date C	leaned		End Time		Additional Info		
		2015	0803		11:05				

Distance	Condition	Cont. Dfct.	Values			laint	Clock Position		Cuada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A26-1								
0.0 ft.	Water Level				5				
4.0 ft.	Tap Factory Made		6		0		3		
7.0 ft.	Tap Factory Made		6		0		9		
49.0 ft.	Tap Factory Made		6		0		3		
230.1 ft.	Water Level				5				
234.1 ft.	Access Point Manhole				0				
Remarks:	A25-3	•							





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A26-1_A25-3	Oliver Springs	Pine st	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A26-1	234.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A25-3	234.1		8	8	4	



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole


Remarks: A26-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 4.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 7.0 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A26-1_A25-3	Oliver Springs	Pine st	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A26-1	234.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A25-3	234.1		8	8	4	ر ا



Distance: 49.0 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 230.1 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 234.1 ft. Grade: 0 Condition:

Access Point Manhole

Remarks: A25-3



## **PACP Conditions**

Pipe Segment Refere		Ci	ty	Street	Mat	erial	Location C	Sewer Use	
A26-1_A25-3		Oliver Springs		Pine st	Concrete Pipe (non		Light High	Sanitary	
Upstream MH		Total Length		Year Laid	Shape		Location Details		
A2	A26-1		4.1		Circ	Circular			
DS Ma	anhole	Length s	urveyed	Year Renewed	Height	Width	Pipe Joint		
A2:	A25-3		4.1		8	8	4		
SPR	N/A	MPR	N/A	PO Number			Customer GRW		
SPRI	N/A	MPRI	N/A	4397-03					
OI IXI	19/74	IVII IXI	11//	Work Order			Purpose		
QSR	N/A	QMR	N/A	4397-02	Pre-Rehabi		Rehabilitation S	habilitation Survey	
OF	PR	Surveyed By		Direction	Date		Media label		
N/	N/A		Rogers	Downstream	20150803				
OF	OPRI		Number	Pre-Cleaning	Time		Weather		
N/	N/A		-16405	Jetting	10:51		Dry		
	Date Cleaned						Additional Info		
		2015	0803	11:05					

		Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		4			4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		0	0		0	0
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code II	D Length									
		Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		   Pi	pe Rating	0	   Pi	pe Rating	0	Overall P	pe Rating	0
		Struct	ural Index	0	0	&M Index	0	Overall Index		0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Quick Rating 00		0000