ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

| Pipe Segment Refere | | City | | Street | Mat | Material | | Sewer Use |
|----------------------|---------------------|--------------------|----------|--------------|-----------------|---------------------------|------------|-----------|
| A27-3_A27-2 | | Oliver Springs | | Springs St | Fibreglass | Fibreglass Reinforc | | Sanitary |
| Upstream MH A27-3 | | Total Length | | Year Laid | Sh | Shape | | Details |
| | | 28 | 2.2 | | Circ | Circular | | |
| DS Ma | DS Manhole A27-2 | | surveyed | Year Renewed | Height | Width | Pipe Joint | |
| A2 | | | 2.2 | | 8 | 8 | N/A | |
| SPR | N/A | MPR | 7 | PO Number | | Customer | | |
| 0001 | | MBDI | | 4397-03 | | | | |
| SPRI | N/A | MPRI | 2.3 | Work Order | | | | |
| QSR | N/A | QMR | 3122 | 4397-02 | | Pre-Rehabilitation Survey | | |
| O | PR . | Surveyed By | | Direction | Di | Date | | alabel |
| 7 | 7 | Charlie Gordon | | Downstream | 2015 | 20150821 | | |
| OF | PRI | Certificate Number | | Pre-Cleaning | Ti | Time | | |
| 2 | 2.3 | | 7000491 | Jetting | 13 | 13:42 End Time | | |
| | | Date C | leaned | End | Additional Info | | | |
| | | 2015 | 0821 | | 14 | :00 | | |

| Distance | Condition | Court Diet | Values | | | | Clock Position | | Overde |
|-----------|-------------------------|-------------|--------|-----|----|-------|----------------|----|--------|
| Distance | Condition | Cont. Dfct. | 1st | 2nd | % | Joint | At/From | То | Grade |
| 0.0 ft. | Access Point Manhole | | | | 0 | | | | |
| Remarks: | A27-3 | | | • | | | | | |
| 0.0 ft. | Water Level | | | | 5 | | | | |
| 8.9 ft. | Tap Factory Made | | 6 | | 0 | | 3 | | |
| 63.1 ft. | Tap Factory Made | | 6 | | 0 | | 9 | | |
| 66.6 ft. | Tap Factory Made | | 6 | | 0 | | 3 | | |
| 82.6 ft. | Tap Factory Made | | 6 | | 0 | | 3 | | |
| 138.6 ft. | Tap Factory Made | | 6 | | 0 | | 3 | | |
| 202.9 ft. | Water Level Sag | | | | 10 | | | | 2 |
| 207.1 ft. | Tap Factory Made | | 6 | | 0 | | 3 | | |
| 269.8 ft. | Water Level Sag | | | | 15 | | | | 2 |
| 273.0 ft. | Water Level Sag | | | | 50 | | | | 3 |
| 276.3 ft. | Tap Factory Made Active | | 6 | | 0 | | 3 | | |
| 279.4 ft. | Water Level | | | | 10 | | | | |
| 282.2 ft. | Access Point Manhole | | | | 0 | | | | |
| Remarks: | A27-2 | | | • | | | | | • |





Image Report 4/Page

| Pipe Segment Refere | City | Street | Material | | Location C | Sewer Use |
|---------------------|-----------------|--------------|---------------------|-------|------------|-----------|
| A27-3_A27-2 | Oliver Springs | Springs St | Fibreglass Reinforc | | Light High | Sanitary |
| Upstream MH | Total Length | Year Laid | Shape | | Location | Details |
| A27-3 | 282.2 | | Circ | ular | | |
| DS Manhole | Length surveyed | Year Renewed | Height | Width | Pipe Joint | |
| A27-2 | 282.2 | | 8 | 8 | N/A | |



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A27-3



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 8.9 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 63.1 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A





Image Report 4/Page

| Pipe Segment Refere | City | Street | Material | | Location C | Sewer Use |
|---------------------|-----------------|--------------|---------------------|-------|------------|-----------|
| A27-3_A27-2 | Oliver Springs | Springs St | Fibreglass Reinforc | | Light High | Sanitary |
| Upstream MH | Total Length | Year Laid | Shape | | Location | Details |
| A27-3 | 282.2 | | Circular | | | |
| DS Manhole | Length surveyed | Year Renewed | Height | Width | Pipe Joint | |
| A27-2 | 282.2 | | 8 | 8 | N/A | |



Distance: 66.6 ft. Grade: 0

Condition: Tap Factory Made


Remarks: N/A



Distance: 82.6 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 138.6 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 202.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Image Report 4/Page

| Pipe Segment Refere | City | Street | Material | | Location C | Sewer Use |
|---------------------|-----------------|--------------|---------------------|-------|------------|-----------|
| A27-3_A27-2 | Oliver Springs | Springs St | Fibreglass Reinforc | | Light High | Sanitary |
| Upstream MH | Total Length | Year Laid | Shape | | Location | Details |
| A27-3 | 282.2 | | Circ | ular | | |
| DS Manhole | Length surveyed | Year Renewed | Height | Width | Pipe Joint | |
| A27-2 | 282.2 | | 8 | 8 | N/A | |



Distance: 207.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 269.8 ft. Grade: 2

Condition: Water Level Sag


Remarks: N/A



Distance: 273.0 ft. Grade: 3

Condition: Water Level Sag

Remarks: N/A



Distance: 276.3 ft. Grade: 0

Condition: Tap Factory Made Active

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

| Pipe Segment Refere | City | Street | Material | | Location C | Sewer Use |
|---------------------|-----------------|--------------|---------------------|-------|------------|-----------|
| A27-3_A27-2 | Oliver Springs | Springs St | Fibreglass Reinforc | | Light High | Sanitary |
| Upstream MH | Total Length | Year Laid | Shape | | Location | Details |
| A27-3 | 282.2 | | Circular | | | |
| DS Manhole | Length surveyed | Year Renewed | Height | Width | Pipe Joint | |
| A27-2 | 282.2 | | 8 | 8 | N/A | |



Distance: 279.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 282.2 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A27-2



PACP Conditions

| Pipe Segment Refere A27-3_A27-2 Upstream MH A27-3 | | City Oliver Springs | | Street | Material Fibreglass Reinforc | | Location C | Sewer Use | |
|---|--------|---------------------|---------|--------------|------------------------------|---------------------------|-------------|-----------|--|
| | | | | Springs St | | | Light High | Sanitary | |
| | | Total | Length | Year Laid | Shape | | Location | Details | |
| | | 282.2 | | | Circular | | | | |
| DS Ma | anhole | Length surveyed | | Year Renewed | Height | Width | Pipe Joint | | |
| A2 | A27-2 | | 2.2 | | 8 | 8 | N/A | | |
| SPR | N/A | MPR | 7 | PO Number | | | Customer | | |
| 0001 | N1/A | | | 4397-03 | | | GRW | | |
| SPRI | N/A | MPRI | 2.3 | Work Order | | | Purpose | | |
| QSR | N/A | QMR | 3122 | 4397-02 | | Pre-Rehabilitation Survey | | | |
| OF | PR | Surveyed By | | Direction | Date | | Media label | | |
| 7 | 7 | Charlie Gordon | | Downstream | 20150821 | | | | |
| OF | PRI | Certificate Number | | Pre-Cleaning | Time | | Weather | | |
| 2 | 2.3 | | 7000491 | Jetting | | 13:42 | | | |
| | | Date C | Cleaned | End Time | | Additional Info | | | |
| | | 2015 | 0821 | | 14:00 | | | | |

| | Structural Ratings | | | 0 | & M Ratin | gs | Com | nbined Ra | ings |
|----------------|--------------------|---------------------------------------|----------------|--|---------------|------------------|--|---------------|------------------|
| Normal Defects | Grade Rating | No. Occur. | Rating | Grade Rating | No. Occur. | Rating | Grade Rating | No. Occur. | Rating |
| | 1 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 0 |
| | 2 | 0 | 0 | 2 | 2 | 4 | 2 | 2 | 4 |
| | 3 | 0 | 0 | 3 | 1 | 3 | 3 | 1 | 3 |
| | 4 | 0 | 0 | 4 | 0 | 0 | 4 | 0 | 0 |
| | 5 | 0 | 0 | 5 | 0 | 0 | 5 | 0 | 0 |
| Code ID Length | | | | | | | | | |
| | Subtotals | 0 | | Subtotals | 3 | | Subtotals | 3 | |
| SUMMARY | Struct | pe Rating ural Index ick Rating | 0 0 0000 | Pipe Rating O&M Index O&M Quick Rating | | 7 2.3 3122 | Overall Pipe Rating Overall Index Ovrl. Quick Rating | | 7 2.3 3122 |