



## Defect Listing

Pipe Segment Refere... <b>A27-4_A27-3</b>	City <b>Oliver Springs</b>	Street <b>Springs ST</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A27-4</b>	Total Length <b>339.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>A27-3</b>	Length surveyed <b>339.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>

SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>	Customer <b>GRW</b>
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>	Purpose <b>Pre-Rehabilitation Survey</b>
QSR <b>N/A</b>	QMR <b>N/A</b>		
OPR <b>N/A</b>	Surveyed By <b>Charlie Gordon</b>	Direction <b>Downstream</b>	Date <b>20150821</b>
OPRI <b>N/A</b>	Certificate Number <b>U-615-07000491</b>	Pre-Cleaning <b>Jetting</b>	Time <b>12:50</b>
	Date Cleaned <b>20150821</b>	End Time <b>13:10</b>	Weather <b>Dry</b>
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A27-4									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
15.2 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
78.3 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
136.7 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
199.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
254.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
336.5 ft.	Water Level				10	<input type="checkbox"/>			
339.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A27-3									




## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A27-4_A27-3	Oliver Springs	Springs ST	Fibreglass Reinforc...	Light High...	Sanitary
Upstream MH A27-4	Total Length 339.4	Year Laid	Shape Circular	Location Details	
DS Manhole A27-3	Length surveyed 339.4	Year Renewed	Height 8	Width 8	Pipe Joint... N/A




Distance: 0.0 ft. Grade: 0  
Condition: Access Point Manhole  
Remarks: A27-4



Distance: 0.0 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A



Distance: 15.2 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 78.3 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




## Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
<b>A27-4_A27-3</b>	<b>Oliver Springs</b>	<b>Springs ST</b>	<b>Fibreglass Reinforc...</b>	<b>Light High...</b>	<b>Sanitary</b>
<b>Upstream MH</b>	Total Length	Year Laid	<b>Shape</b>	Location Details	
<b>A27-4</b>	<b>339.4</b>		<b>Circular</b>		
<b>DS Manhole</b>	<b>Length surveyed</b>	Year Renewed	<b>Height</b>	Width	Pipe Joint...
<b>A27-3</b>	<b>339.4</b>		<b>8</b>	<b>8</b>	<b>N/A</b>




Distance: 136.7 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 199.0 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A



Distance: 254.4 ft. Grade: 0  
Condition: Tap Factory Made  
Remarks: N/A




Distance: 336.5 ft. Grade: 0  
Condition: Water Level  
Remarks: N/A





## Image Report 4/Page

Pipe Segment Refere... <b>A27-4_A27-3</b>	<b>City</b> <b>Oliver Springs</b>	<b>Street</b> <b>Springs ST</b>	<b>Material</b> <b>Fibreglass Reinforc...</b>		<b>Location C...</b> <b>Light High...</b>	<b>Sewer Use</b> <b>Sanitary</b>
<b>Upstream MH</b> <b>A27-4</b>	Total Length <b>339.4</b>	Year Laid	<b>Shape</b> <b>Circular</b>		Location Details	
<b>DS Manhole</b> <b>A27-3</b>	<b>Length surveyed</b> <b>339.4</b>	Year Renewed	<b>Height</b> <b>8</b>	Width <b>8</b>	Pipe Joint...	<b>N/A</b>



Distance: 339.4 ft.      Grade: 0  
Condition: Access Point Manhole  
Remarks: A27-3



## PACP Conditions

Pipe Segment Refere... <b>A27-4_A27-3</b>	City <b>Oliver Springs</b>	Street <b>Springs ST</b>	Material <b>Fibreglass Reinforc...</b>	Location C... <b>Light High...</b>	Sewer Use <b>Sanitary</b>
Upstream MH <b>A27-4</b>	Total Length <b>339.4</b>	Year Laid	Shape <b>Circular</b>	Location Details	
DS Manhole <b>A27-3</b>	Length surveyed <b>339.4</b>	Year Renewed	Height <b>8</b>	Width <b>8</b>	Pipe Joint... <b>N/A</b>
SPR <b>N/A</b>	MPR <b>N/A</b>	PO Number <b>4397-03</b>		Customer <b>GRW</b>	
SPRI <b>N/A</b>	MPRI <b>N/A</b>	Work Order <b>4397-02</b>		Purpose <b>Pre-Rehabilitation Survey</b>	
QSR <b>N/A</b>	QMR <b>N/A</b>	Direction <b>Downstream</b>		Date <b>20150821</b>	
OPR <b>N/A</b>	Surveyed By <b>Charlie Gordon</b>	Pre-Cleaning <b>Jetting</b>		Media label	
OPRI <b>N/A</b>	Certificate Number <b>U-615-07000491</b>	Time <b>12:50</b>		Weather <b>Dry</b>	
Date Cleaned <b>20150821</b>			End Time <b>13:10</b>		Additional Info

Normal Defects			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									