ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A28-1_A27-3		Oliver Springs		Union Dr	Concrete F	ipe (non	Light High	Sanitary	
Upstream MH Total L		_ength	Year Laid	Shape		Location Details			
A2	8-1	99	0.6		Circular				
DS Manhole		Length surveyed		Year Renewed	Height Width		Pipe Joint		
A2	7-3	99	0.6		8 8 4				
SPR	5	MPR	8	PO Number	PO Number		Customer		
				4397-03		GRW			
SPRI	5	MPRI	2.7	Work Order	Work Order		Purpose		
QSR	5100	QMR	4131	4397-02		Pre-	e-Rehabilitation Survey		
0	PR	Surve	yed By	Direction	Date		Media label		
1	3	Charlie Gordon		Downstream	20150821				
Ol	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
3.3		U-615-07000491		Jetting	08:15		Damp		
		Date C	leaned		End Time Add		Addition	nal Info	
		2015	0821		08:23				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		0
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A28-1			•	•				
0.0 ft.	Water Level				5				
34.2 ft.	Roots Fine Joint				0	✓	12		1
34.2 ft.	Infiltration Runner				0		1		4
81.3 ft.	Hole Soil Visible				0		2		5
81.3 ft.	Infiltration Dripper				0		3		3
81.3 ft.	Infiltration Stain						2	6	
97.5 ft.	Water Level				10				
99.6 ft.	Access Point Manhole				0				
Remarks:	A27-3			•			•		





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A28-1_A27-3	Oliver Springs	Union Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A28-1	99.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A27-3	99.6		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A28-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 34.2 ft. Grade: 1

Condition: Roots Fine Joint

Remarks: N/A



Distance: 34.2 ft. Grade: 4

Condition: Infiltration Runner


Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A28-1_A27-3	Oliver Springs	Union Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A28-1	99.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A27-3	99.6		8	8	4	



Distance: 81.3 ft. Condition:

Hole Soil Visible

Remarks: N/A



Distance: 81.3 ft. Grade: 3

Condition: Infiltration Dripper

Remarks: N/A



Distance: 81.3 ft. Grade: 0

Condition: Infiltration Stain

Remarks: N/A



Distance: 97.5 ft. Grade: 0

Condition: Water Level


Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A28-1_A27-3	Oliver Springs	Union Dr	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A28-1	99.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A27-3	99.6		8	8	4	



Distance: 99.6 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A27-3



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A28-1_	_A27-3	Oliver	Springs	Union Dr	Concrete P	Pipe (non	Light High	Sanitary	
Upstrea	am MH	Total Length		Total Length Year Laid Shape		ape Location De		n Details	
A2	8-1	99	99.6 Circular						
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	th Pipe Joint		
A2	7-3	99	9.6		8 8		4		
SPR	5	MPR	8	PO Number	per		Customer		
SPRI	5	MPRI	2.7	4397-03 Work Order			GRW Purpose		
JEKI		IVIFIXI	2.1						
QSR	5100	QMR	4131	4397-02		Pre-	-Rehabilitation Survey		
OF	PR	Surveyed By		Direction	Date		Media label		
1	3	Charlie Gordon		Downstream	20150821				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
3.3		U-615-07000491		Jetting	08:15		Damp		
		Date C	Cleaned		End Time		Additional Info		
		2015	0821		08:23				

		Stru	ctural Rat	ings	О	& M Ratin	gs	Con	nbined Ra	tings
Normal D	efects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		1	_	0	1	4	4	1	4	4
		2	0	0	2	1	0	2	1	1
		3	0	0	3	0	3	3	0	3
		4	0	0	4	1	4	4	1	4
		5	1	5	5	0	0	5	1	5
						-				
Continuous	Defects									
Code ID	Length									
		Subtotals	1		Subtotals	3		Subtotals	4	
SUMMARY		Pi	pe Rating	5	Pipe Rating		8	Overall P	pe Rating	13
GOIVIIVI	ואוי		ural Index	5.0		&M Index	2.7		erall Index	3.3
		Str. Qu	ick Rating	5100	O&M Qui	ick Rating	4131	Ovrl. Qu	ick Rating	5141