ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



# **Defect Listing**

Pipe Segment Refere		С	ity	Street	Mat	Material		Sewer Use
A31-2_A31-1 Oliver Springs		Van hook Ct.	Concrete F	Concrete Pipe (non		Sanitary		
Upstre	am MH	Total	Length	Year Laid	Sh	Shape Circular		Details
A3	1-2	20	9.6		Circ			
DS M	anhole	Length surveyed 209.6		Year Renewed	Height	Width	Pipe Joint	
A3	1-1				8	8	4	
SPR	6	MPR	12	4397-03 GR		Customer		
						GRW Purpose		
SPRI	3	MPRI	2					
QSR	3200	QMR	2600	4397-02		Pre-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Da	ate	Media label	
1	8	Charlie Gordon		Downstream	2015	20150825		
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
2	2.3		7000491	Jetting	15	15:06 I End Time		
		Date C	Cleaned	End				Additional Info
20150825					15:21			

Distance	Condition	Cant Diat	Values			laint	Clock Position		Crada
Distance	Condition	Cont. Dfct.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A31-2				•		'		•
0.0 ft.	Water Level				5				
41.1 ft.	Water Level Sag				10				2
45.6 ft.	Tap Factory Made		6		0		11		
46.1 ft.	Hole						8		3
78.7 ft.	Water Level Sag				10				2
92.1 ft.	Tap Factory Made		6		0		3		
123.9 ft.	Water Level Sag				10				2
126.1 ft.	Surface Aggregate Visible Unknown					<b>/</b>	1	9	3
131.3 ft.	Water Level Sag				15				2
144.2 ft.	Tap Factory Made		6		0		11		
181.6 ft.	Water Level Sag				15				2
200.7 ft.	Water Level Sag				15				2
206.8 ft.	Water Level				10				
209.6 ft.	Access Point Manhole				0				
Remarks:	A31-1						1		1





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A31-2_A31-1	Oliver Springs	Van hook Ct.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A31-2	209.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A31-1	209.6		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A31-2



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 41.1 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 45.6 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A31-2_A31-1	Oliver Springs	Van hook Ct.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A31-2	209.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A31-1	209.6		8	8	4	



Distance: 46.1 ft


Condition: Hole Remarks: N/A



Distance: 78.7 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 92.1 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 123.9 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A31-2_A31-1	Oliver Springs	Van hook Ct.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A31-2	209.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A31-1	209.6		8	8	4	



Distance: 126.1 ft. Grade: 3

Condition: Surface Aggregate Visible Unknown

Remarks: N/A



Distance: 131,3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 144.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 181.6 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A





Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A31-2_A31-1	Oliver Springs	Van hook Ct.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A31-2	209.6		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A31-1	209.6		8	8	4	ر ا



Distance: 200,7 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 206.8 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 209.6 ft. Grade: 0
Condition: Access Point Manhole

Remarks: A31-1



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A31-2_A31-1 Oliver Springs		Van hook Ct.	Concrete F	Concrete Pipe (non		Sanitary			
Upstrea	am MH	Total I	Length	Year Laid	Sh	Shape		Details	
A3	1-2	20	9.6		Circ	cular			
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A3	1-1	209.6			8	8	4		
SPR	6	MPR	12	PO Number					
SPRI	3	MPRI	2	4397-03	4397-03		GRW		
SFRI	<b>3</b>	IVIFKI		Work Order		Purpose			
QSR	3200	QMR	2600	4397-02		Pre-	-Rehabilitation Survey		
OF	PR	Surveyed By		Direction	Di	ate	Media label		
1	8	Charlie Gordon		Downstream	2015	20150825			
OF	OPRI		e Number	Pre-Cleaning	Ti	Time			
2.	2.3		7000491	Jetting	15	15:06			
	Date Cleaned			End <sup>-</sup>		End Time		nal Info	
		2015	0825		15	15:21			

		Structural Ratings			О	& M Ratin	gs	Con	nbined Ra	tings
Normal D	efects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
		1	0	0	4	0		4	0	0
		2	0	0	2	0	0	2	0	0
		3	0	0	3	6	12	3	6	12
		4	2	6	4	0	0	4	2	6
			0	0		0	0		0	0
		5	0	0	5	0	0	5	0	0
Continuous	s Defects									
Code ID	Length									
		Subtotals	2		Subtotals	6		Subtotals	8	
SUMMARY		Pi	ipe Rating	6	Pi	pe Rating	12	Overall Pi	pe Rating	18
		Struct	ural Index	3.0	0	&M Index	2.0	Ove	erall Index	2.3
		Str. Qu	ick Rating	3200	O&M Qui	ick Rating	2600	Ovrl. Qu	ick Rating	3226