ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



# **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use		
A32-3_A32-2		Oliver Springs		Green St	Concrete Pipe (non		Light High	Sanitary		
Upstre	am MH	Total I	Length	Year Laid	Sh	ape	pe Location Detai			
A3	2-3	30	3.8		Circ	ular				
DS M	anhole	Length s	surveyed	Year Renewed	Height	Width Pipe Joint				
A3	2-2	30	3.8		8	8	8 4			
SPR	1	MPR	4	PO Number			Customer			
	· · ·			4397-03	4397-03			GRW		
SPRI	1	MPRI	4	Work Order		Purpose				
QSR	1100	QMR	4100	4397-02	Pre-Rehabilitation		Rehabilitation S	tation Survey		
0	PR	Surve	yed By	Direction	Da	ate	Media	label		
	5	Barry_	Rogers	Downstream	20150728					
Ol	PRI	Certificat	e Number	Pre-Cleaning	Time		Weather			
2	2.5 U-1012-16405		2-16405	Jetting	12:01		Dry			
		Date C	leaned		End Time		Additional Info			
		2015	0728		12:14					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock P	osition	Grada
	Condition	Cont. Dict.	1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A32-3								•
0.0 ft.	Water Level				5				
2.0 ft.	Joint Offset Medium				0				1
2.0 ft.	Infiltration Runner				0		8		4
81.2 ft.	Tap Factory Made		6		0		9		
109.4 ft.	Tap Factory Made		6		0		9		
206.3 ft.	Tap Saddle		6		0		10		
Remarks:	Debris inside Tap								•
300.4 ft.	Tap Factory Made		6		0		9		
300.4 ft.	Water Level				5				
303.8 ft.	Access Point Manhole				0				
Remarks:	A32-2								-





#### Image Report 4/Page

(	Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
	A32-3_A32-2	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary
	Upstream MH	Total Length	Year Laid	Shape		Location	Details
	A32-3	303.8		Circular			
	DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
	A32-2	303.8		8	8	4	,



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole


Remarks: A32-3



Distance: 0.0 ft. Grade: 0

Condition: Water Level


Remarks: N/A



Distance: 2.0 ft. Grade: 1

Condition: Joint Offset Medium

Remarks: N/A



Distance: 2.0 ft. Grade: 4

Condition: Infiltration Runner

Remarks: N/A





#### **Image Report 4/Page**


Pipe Segment Refere	City	Street	Mat	Material		Sewer Use
A32-3_A32-2	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A32-3	303.8		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A32-2	303.8		8	8	4	



Distance: 81.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 109.4 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 206.3 ft. Grade: 0

Condition: Tap Saddle
Remarks: Debris inside Tap



Distance: 300.4 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



### Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A32-3_A32-2	Oliver Springs	Green St	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A32-3	303.8		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A32-2	303.8		8	8	4	,



Distance: 300.4 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 303.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A32-2



## **PACP Conditions**

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A32-3_A32-2		Oliver Springs		Green St	Concrete Pipe (non		Light High	Sanitary	
Upstre	Upstream MH		Length	Year Laid	Shape		Location	Details	
A3	2-3	30	3.8		Circular				
DS M	anhole	Length:	surveyed	Year Renewed	Height	Width	Width Pipe Joint 8 4		
A3	2-2	30	3.8		8	8			
SPR	1	MPR	4	PO Number			Customer		
0001				4397-03	GRW				
SPRI	1	MPRI	4	Work Order	Purpose		Purpose		
QSR	1100	QMR	4100	4397-02		Pre-	Rehabilitation S	urvey	
0	PR	Surve	yed By	Direction	Da	ate	Media	label	
;	5	Barry_	Rogers	Downstream	20150728				
O	PRI	Certificat	e Number	Pre-Cleaning	Time		Weather		
2	2.5 U-1012-16405		Jetting 1		12:01				
		Date C	Cleaned			End Time		Additional Info	
		2015	0728		12:14				

	Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	1	1	1	0	0	1	1	1
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	1	4	4	1	4
	5	0	0	5	0	0	5	0	0
Continuous Defects  Code ID Length									
	Subtotals	1		Subtotals	1		Subtotals	2	
SUMMARY	Pipe Rating 1 Structural Index 1.(		1 1.0 1100	Pipe Rating O&M Index O&M Quick Rating		4 4.0 4100	Overall Pipe Rating Overall Index Ovrl. Quick Rating		5 2.5 4111