



Defect Listing

Pipe Segment Refere... A35-2_A35-1	City Oliver Springs	Street Wiley St.	Material Fibreglass Reinforc...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A35-2	Total Length 258.6	Year Laid	Shape Circular	Location Details	
DS Manhole A35-1	Length surveyed 258.6	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR N/A	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR N/A		
OPR N/A	Surveyed By Charlie Gordon	Direction Downstream	Date 20150826
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 07:40
	Date Cleaned 20150826	End Time 07:53	Weather Dry
		Additional Info Mh A36-1_A36-2 Does...	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A35-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
54.6 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	3		
255.7 ft.	Water Level				10	<input type="checkbox"/>			
258.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A35-1									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A35-2_A35-1	Oliver Springs	Wiley St.	Fibreglass Reinforc...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A35-2	258.6		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A35-1	258.6		8	8	N/A




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A35-2



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 54.6 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A




Distance: 255.7 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A35-2_A35-1	City Oliver Springs	Street Wiley St.	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A35-2	Total Length 258.6	Year Laid	Shape Circular		Location Details	
DS Manhole A35-1	Length surveyed 258.6	Year Renewed	Height 8	Width 8	Pipe Joint...	N/A



Distance: 258.6 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A35-1



Pipe Segment Refere... A35-2_ A35-1	City Oliver Springs	Street Wiley St.	Material Fibreglass Reinforc...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A35-2	Total Length 258.6	Year Laid	Shape Circular		Location Details	
DS Manhole A35-1	Length surveyed 258.6	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose		
QSR N/A	QMR N/A			Pre-Rehabilitation Survey		
OPR N/A	Surveyed By Charlie Gordon	Direction Downstream	Date 20150826		Media label	
OPRI N/A	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 07:40		Weather Dry	
Date Cleaned 20150826			End Time 07:53		Additional Info Mh A36-1 A36-2 Does...	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Code	ID	Length									