

Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use		
A37-2_A37-1		Oliver Springs		Hen Valley	Concrete F	Concrete Pipe (non		Sanitary		
Upstream MH		Total Length		Year Laid	Sh	ape	Location Details			
A37-2		113.7			Circ	cular				
DS Manhole		Length surveyed		Year Renewed Height		Width	Pipe Joint			
A37-1		113.7			8	8	4			
SPR	N/A	MPR	N/A	PO Number			Customer			
0001	N1/A	MDDI	NIZA	4397-03		GRW				
SPRI	N/A	MPRI	N/A	Work Order				Purpose		
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey				
OF	OPR		red By	Direction	Date		Media label			
N/	N/A		Rogers	Upstream	20150810					
OP	OPRI		e Number	Pre-Cleaning	Time		Weather			
N/A		U-1012-16405		Jetting	07:48		Dry			
		Date C	leaned		End Time		Additional Info			
		2015	0810	07						

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A37-1								
0.0 ft.	Water Level				5				
44.2 ft.	Tap Factory Made		6		0		9		
113.7 ft.	Survey Abandoned				0				
Remarks:	MADE TO THE INTRUDING TAP								





Image Report 4/Page

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
A37-2_A37-1	Oliver Springs	Hen Valley	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A37-2	113.7		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A37-1	113.7		8	8	4	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A37-1



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 44.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 113.7 ft. Grade: 0

Condition: Survey Abandoned

Remarks: MADE TO THE INTRUDING TAP



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A37-2_A37-1		Oliver Springs		Hen Valley	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH A37-2		Total Length 113.7		Year Laid	Sh	Shape Circular		Details	
					Circ				
DS Ma	anhole	Length s	surveyed	Year Renewed	Renewed Height Width Pipe Joint		Pipe Joint		
A3	A37-1		3.7		8	8	4		
SPR	N/A	MPR	N/A	PO Number		Customer			
SPRI	N/A	MPRI	N/A	4397-03					
SPRI	IN/A	IVIFKI	IN/A	Work Order	r				
QSR	N/A	QMR	N/A	4397-02		Pre-Rehabilitation Survey			
OF	PR	Surveyed By		Direction	D	Date		Media label	
N	/A	Barry_Rogers		Upstream	2015	20150810			
OF	OPRI		e Number	Pre-Cleaning	Ti	Time			
N/A		U-1012-16405		Jetting	07	07:48			
		Date C	leaned		End	End Time		Additional Info	
		2015	0810	07	07:55				

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			4			4			4		
			2	0	0	2	0	0	2	0	0
				0	0		0	0		0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu	ous C	Defects									
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	0	Overall Pipe Rati		0	
30			Struct	ural Index	0	O&M Index		0	Overall Index		0
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000