



Defect Listing

Pipe Segment Refere... A41-1_A40-1	City Oliver Springs	Street Hill Cir	Material Concrete Pipe (non-...	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A41-1	Total Length 240.2	Year Laid	Shape Circular	Location Details	
DS Manhole A40-1	Length surveyed 240.2	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR 1	MPR 8	PO Number 4397-03		Customer GRW	
SPRI 1	MPRI 4	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR 1100	QMR 4200				
OPR 9	Surveyed By Charlie Gordon	Direction Downstream	Date 20150820	Media label	
OPRI 3	Certificate Number U-615-07000491	Pre-Cleaning Jetting	Time 09:00	Weather Damp	
Date Cleaned 20150820			End Time 09:17	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A41-1									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
100.1 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
108.6 ft.	Infiltration Runner				0	<input checked="" type="checkbox"/>	10		4
189.5 ft.	Joint Offset Medium				0	<input type="checkbox"/>			1
189.5 ft.	Infiltration Runner				0	<input type="checkbox"/>	11		4
238.4 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	6		
238.4 ft.	Water Level				10	<input type="checkbox"/>			
240.2 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A40-1									




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A41-1_A40-1	Oliver Springs	Hill Cir	Concrete Pipe (non-...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A41-1	240.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A40-1	240.2		8	8	4




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A41-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 100.1 ft. Grade: 0
Condition: Tap Factory Made
Remarks: N/A




Distance: 108.6 ft. Grade: 4
Condition: Infiltration Runner
Remarks: N/A




Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A41-1_A40-1	Oliver Springs	Hill Cir	Concrete Pipe (non-...	Easement/R...	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A41-1	240.2		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A40-1	240.2		8	8	4




Distance: 189.5 ft. Grade: 1
Condition: Joint Offset Medium
Remarks: N/A



Distance: 189.5 ft. Grade: 4
Condition: Infiltration Runner
Remarks: N/A



Distance: 238.4 ft. Grade: 0
Condition: Tap Factory Made Active
Remarks: N/A




Distance: 238.4 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A41-1_A40-1	City Oliver Springs	Street Hill Cir	Material Concrete Pipe (non-...		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A41-1	Total Length 240.2	Year Laid	Shape Circular		Location Details	
DS Manhole A40-1	Length surveyed 240.2	Year Renewed	Height 8	Width 8	Pipe Joint...	4



Distance: 240.2 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A40-1



Albuquerque, NM

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects Code ID Length 			1	1	1	1	0	0	1	1	1
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	2	8	4	2	8
			5	0	0	5	0	0	5	0	0
			Subtotals	1		Subtotals	2		Subtotals	3	
SUMMARY			Pipe Rating	1		Pipe Rating	8		Overall Pipe Rating	9	
			Structural Index	1.0		O&M Index	4.0		Overall Index	3.0	
			Str. Quick Rating	1100		O&M Quick Rating	4200		Ovrl. Quick Rating	4211	