ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Defect Listing

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use	
A43-1_A6-19A		Oliver Springs		Highway 61	Concrete F	Concrete Pipe (non		Sanitary	
Upstream MH A43-1		Total Length 174.4		Year Laid	Shape Circular		Location Details		
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint		
A6-19A		174.4			8	8	4		
SPR	7	MPR	6	PO Number 4397-03			Customer		
CDDI	2.5	MDDI	2			G		GRW	
SPRI	3.5	MPRI	3	Work Order			Purpose		
QSR	5121	QMR	4121	4397-02		Pre-		urvey	
OI	PR	Surveyed By		Direction	Date		Media label		
1	3	Charlie_Gordon		Upstream	20150901				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
3.3		U-615-07000491		Jetting	10:27		Dry		
		Date C	leaned		End Time		Additional Info		
		2015	0901		10:38				

Distance	Condition	Cont. Dfct.	Values			laint	Clock Position		Overde
	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A6-19								
0.0 ft.	Water Level				5				
169.3 ft.	Water Level Sag				10				2
174.2 ft.	Hole Soil Visible				0		9	3	5
174.2 ft.	Infiltration Runner				0		9	3	4
174.4 ft.	Joint Offset Large				0				2
174.4 ft.	Survey Abandoned				0				
Remarks:	cannot pass offset joint	•							





Image Report 4/Page

Pipe Segment Refere	Pipe Segment Refere City		Material		Location C	Sewer Use
A43-1_A6-19A	Oliver Springs	Highway 61	Concrete Pipe (non		Main Highw	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A43-1	174.4		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A6-19A	174.4		8	8	4	,



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole

Remarks: A6-19



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 169.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 174.2 ft. Grade: 5

Condition: Hole Soil Visible

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A43-1_A6-19A	Oliver Springs	Highway 61	Concrete Pipe (non		Main Highw	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A43-1	174.4		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A6-19A	174.4		8	8	4	



Distance: 174,2 ft. Grade: 4

Condition: Infiltration Runner


Remarks: N/A



Distance: 174.4 ft. Grade: 2

Condition: Joint Offset Large

Remarks: N/A



Distance: 174.4 ft. Grade: 0

Condition: Survey Abandoned **Remarks:** cannot pass offset joint



PACP Conditions

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use
A43-1_A6-19A		Oliver Springs		Highway 61	Concrete Pipe (non		Main Highw	Sanitary
Upstream MH		Total Length		Year Laid	Shape		Location Details	
A43-1		174.4			Circ	cular		
DS M	DS Manhole		surveyed	Year Renewed	Height	Width	Pipe Joint	
A6-	A6-19A		4.4		8	8	4	
SPR	7	MPR	6	PO Number			Customer	
2001				4397-03 Work Order		GRW		
SPRI	3.5	MPRI	3			Purpose		
QSR	5121	QMR	4121	4397-02	Pre		-Rehabilitation Survey	
Ol	PR	Surveyed By		Direction	Date		Media label	
1	3	Charlie_Gordon		Upstream	20150901			
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather	
3	3.3		7000491	Jetting	10:27		Dry	
		Date C	Cleaned		End Time		Additional Info	
		2015	0901	10:38				

	Stru	Structural Ratings			& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	0	0	1	0	0
	2	1	2	2	1	2	2	2	4
	3	0	0	3	0	0	3	0	0
	4	0	0	4	1	4	4	1	4
	5	1	5	5	0	0	5	1	5
Code ID Length									
	Subtotals	2		Subtotals	2		Subtotals	4	
SUMMARY	Struct	ipe Rating ural Index ick Rating		0	pe Rating &M Index ick Rating	6 3.0 4121	Ove	ipe Rating erall Index ick Rating	13 3.3 5141