

Defect Listing

505-341-0109


Pipe Segme	Pipe Segment Refere		ity	Street	Mat	erial	Location C	Sewer Use	
A5-1_	_A-41	Oliver	Springs	Burney Dr	Concrete F	e Pipe (non Yard		Sanitary	
Upstre	am MH	Total	Length	Year Laid	Shape		Location Details		
AS	5-1	45	5.3		Circular				
DS Ma	anhole	Length :	surveyed	Year Renewed	Height	Width	Pipe Joint		
A-	41	45	5.3		8	8	4		
SPR	N/A	MPR	3	PO Number			Customer		
SPRI	N/A	MPRI	3	4397-03			GRW		
0110	IN/A		5	Work Order					
QSR	N/A	QMR	3100	4397-02		Pre-	Rehabilitation S	abilitation Survey	
O	PR	Surveyed By		Direction	Da	Date		a label	
3	3	Charlie_Gordon		Downstream	20150901				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
3	3		7000491	No Pre-Cleaning	07:51		Dry		
	Date Cleaned					End Time		nal Info	
					07	:57			


Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A5-1								
0.0 ft.	Water Level				5				
43.7 ft.	Roots Medium Joint				40		7	5	3
44.9 ft.	Water Level				5				
45.3 ft.	Access Point Manhole				0				
Remarks:	A-41								




Image Report 4/Page

Pipe Segment Refere	City	ty Street Material		Location C	Sewer Use	
A5-1_A-41	Oliver Springs	Burney Dr	Concrete Pipe (non		Yard	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A5-1	45.3	5.3 Circular				
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-41	45.3		8	8	4	












ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109

Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A5-1_A-41	Oliver Springs	Burney Dr	Concrete F	Concrete Pipe (non		Sanitary
Upstream MH	Total Length	Year Laid	Sh	Shape		Details
A5-1	45.3		Circular			
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A-41	45.3		8	8	4	





PACP Conditions

Pipe Segme	ent Refere	C	ity	Street	Mat	erial	Location C	Sewer Use
A5-1_	_A-41	Oliver	Springs	Burney Dr	Concrete F	ncrete Pipe (non Yard		Sanitary
Upstre	am MH	Total	Length	Year Laid	Sha	Shape Location D		n Details
A	5-1	45	5.3		Circular			
DS M	anhole	Length :	surveyed	Year Renewed	Height	Width	Pipe Joint	
A-	-41	45	5.3		8	8	4	
SPR	N/A	MPR	3	PO Number	3		Customer GRW Purpose	
SPRI	N/A	MPRI	3	4397-03				
or Ki	11/A		J	Work Order				
QSR	N/A	QMR	3100	4397-02		Pre-F	Rehabilitation Survey	
OI	PR	Surveyed By		Direction	Date		Media label	
;	3	Charlie_Gordon		Downstream	20150901			
OF	PRI	Certificat	e Number	Pre-Cleaning	Time		Weather	
;	3 U-615-07000491		7000491	No Pre-Cleaning	07:51		Dry	
	Date Cleaned					Time	Additional Info	
					07	:57		

			Structural Ratings			0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	1	3	3	1	3
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continue Code	ID	Length									
			Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		Struct	pe Rating ural Index ick Rating	0 0 0000	0	pe Rating &M Index ick Rating	3 3.0 3100	Ov	ipe Rating erall Index iick Rating	3 3.0 3100	