



Defect Listing

Pipe Segment Refere... A6-1_A-46	City Oliver Springs	Street Main St.	Material Fibreglass Reinforc...	Location C... Creek	Sewer Use Sanitary
Upstream MH A6-1	Total Length 11	Year Laid	Shape Circular	Location Details	
DS Manhole A-46	Length surveyed 11	Year Renewed	Height 8	Width 8	Pipe Joint... N/A


SPR N/A	MPR 4	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI 4	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR 4100				
OPR 4	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150902	Media label	
OPRI 4	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 07:07	Weather Dry	
Date Cleaned			End Time 07:12	Additional Info DEPOSITS UNDERWATER..	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A6-1									
0.0 ft.	Water Level				50	<input type="checkbox"/>			
0.5 ft.	Camera Underwater					<input type="checkbox"/>			4
11.0 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: DEPOSITS UNDERWATER									




Image Report 4/Page

Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A6-1_A-46	Oliver Springs	Main St.	Fibreglass Reinforc...	Creek	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A6-1	11		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-46	11		8	8	N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A6-1



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 0.5 ft. Grade: 4
Condition: Camera Underwater
Remarks: N/A



Distance: 11.0 ft. Grade: 0
Condition: Survey Abandoned
Remarks: DEPOSITS UNDERWATER



Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A6-1_A-46	Oliver Springs	Main St.	Fibreglass Reinforc...	Creek	Sanitary
Upstream MH	Total Length	Year Laid	Shape	Location Details	
A6-1	11		Circular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint...
A-46	11		8	8	N/A
SPR	N/A	MPR	4	Customer	
SPRI	N/A	MPRI	4	GRW	
QSR	N/A	QMR	4100	Purpose	
OPR	Surveyed By	Direction	Date	Media label	
4	Charlie_Gordon	Downstream	20150902		
OPRI	Certificate Number	Pre-Cleaning	Time	Weather	
4	U-615-07000491	No Pre-Cleaning	07:07	Dry	
Date Cleaned			End Time	Additional Info	
			07:12	DEPOSITS UNDERWATER..	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects			1	0	0	1	0	0	1	0	0
			2	0	0	2	0	0	2	0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	1	4	4	1	4
			5	0	0	5	0	0	5	0	0
Code	ID	Length									