



Defect Listing

Pipe Segment Refere... A6-16_A6-16A	City Oliver Springs	Street 61 HIGHWAY	Material Fibreglass Reinforc...	Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A6-16	Total Length 303.1	Year Laid	Shape Circular	Location Details	
DS Manhole A6-16A	Length surveyed 303.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A

SPR N/A	MPR 2	PO Number 4397-03	Customer GRW
SPRI N/A	MPRI 2	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR N/A	QMR 2100		
OPR 2	Surveyed By Barry Rogers	Direction Downstream	Date 20150810
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:01
	Date Cleaned 20150810	End Time 10:04	Weather Dry
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	☐			
Remarks: A6-16									
0.0 ft.	Water Level				10	☐			
300.0 ft.	Water Level				5	☐			
300.1 ft.	Roots Fine Barrell					☐	7	10	2
300.1 ft.	Infiltration Stain					☐	2	5	
300.1 ft.	Infiltration Stain					☐	8	10	
303.1 ft.	Access Point Manhole				0	☐			
Remarks: A6-15									



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A6-16_A6-16A	Oliver Springs	61 HIGHWAY	Fibreglass Reinforc...	Main Highw...	Sanitary
Upstream MH A6-16	Total Length 303.1	Year Laid	Shape Circular	Location Details	
DS Manhole A6-16A	Length surveyed 303.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A



Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A6-16



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 300.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A




Distance: 300.1 ft. Grade: 2
Condition: Roots Fine Barrell
Remarks: N/A



Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A6-16_A6-16A	Oliver Springs	61 HIGHWAY	Fibreglass Reinforc...	Main Highw...	Sanitary
Upstream MH A6-16	Total Length 303.1	Year Laid	Shape Circular	Location Details	
DS Manhole A6-16A	Length surveyed 303.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A




Distance: 300.1 ft. Grade: 0
Condition: Infiltration Stain
Remarks: N/A



Distance: 300.1 ft. Grade: 0
Condition: Infiltration Stain
Remarks: N/A



Distance: 303.1 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A6-15



Pipe Segment Refere... A6-16_A6-16A	City Oliver Springs	Street 61 HIGHWAY	Material Fibreglass Reinforc...		Location C... Main Highw...	Sewer Use Sanitary
Upstream MH A6-16	Total Length 303.1	Year Laid	Shape Circular		Location Details	
DS Manhole A6-16A	Length surveyed 303.1	Year Renewed	Height 8	Width 8	Pipe Joint... N/A	
SPR N/A	MPR 2	PO Number 4397-03		Customer GRW		
SPRI N/A	MPRI 2	Work Order 4397-02		Purpose		
QSR N/A	QMR 2100			Pre-Rehabilitation Survey		
OPR 2	Surveyed By Barry_Rogers	Direction Downstream	Date 20150810		Media label	
OPRI 2	Certificate Number U-1012-16405	Pre-Cleaning Jetting	Time 10:01		Weather Dry	
Date Cleaned 20150810			End Time 10:04		Additional Info	

			Structural Ratings			O & M Ratings			Combined Ratings		
			Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
Normal Defects											
Continuous Defects CodeIDLength			1	0	0	1	0	0	1	0	0
			2	0	0	2	1	2	2	1	2
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
			Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY			Pipe Rating Structural Index Str. Quick Rating	0 0 0000		Pipe Rating O&M Index O&M Quick Rating	2 2.0 2100		Overall Pipe Rating Overall Index Ovrl. Quick Rating	2 2.0 2100	