

Defect Listing

Pipe Segment Refere		City		Street	Ma	terial	Location C	Sewer Use	
A6-23_A6-22		Oliver Springs		708 Hen Valley Rd.	Concrete I	Concrete Pipe (non		Sanitary	
Upstream MH T		Total I	_ength	Year Laid	Sh	ape	Location	n Details	
A6-	23	20)3		Circ	cular	Middle of road		
DS Ma	inhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A6-	A6-22)3		8	8	4		
SPR	N/A	MPR	1	PO Number		Customer			
0001	-			4397-03		GRW			
SPRI	N/A	MPRI	1	Work Order			Purpose		
QSR	N/A	QMR	1100	4397-02		Pre-Rehabilitation Survey			
OF	PR	Survey	ed By	Direction	Date		Media label		
1	1 Dustin		stin	Downstream	20150807				
OPRI		Certificate Number		Pre-Cleaning	Time		Weather		
1		U-214-06020262		Jetting	13:57		Dry		
	Date Cleaned					End Time		Additional Info	
		2015	0807	14:12					

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		0
Distance	Condition		1st	2nd	%	Jonn	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A6-23 EOL								•
0.0 ft.	Water Level				5				
2.0 ft.	Roots Fine Joint				0	4	5	8	1
24.2 ft.	Tap Factory Made		4		0	4	3		
63.2 ft.	Tap Factory Made		4		0	4	3		
152.3 ft.	Water Level				5				
172.3 ft.	Tap Factory Made		4		0	4	3		
201.9 ft.	Water Level				5				
203.0 ft.	Access Point Manhole				0				
Remarks:	A6-22							•	•





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A6-23_A6-22	Oliver Springs	708 Hen Valley Rd.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Shape Location [
A6-23	203		Circular		Middle	of road
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A6-22	203		8	8	4	



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole


Remarks: A6-23 EOL



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 2.0 ft. Grade: 1

Condition: Roots Fine Joint

Remarks: N/A



Distance: 24.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A





Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A6-23_A6-22	Oliver Springs	708 Hen Valley Rd.	Concrete Pipe (non		Light High	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Shape Location [
A6-23	203		Circular		Middle	of road
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A6-22	203		8	8	4	



Distance: 63.2 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 152.3 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 172.3 ft. Grade: 0

Condition: Tap Factory Made

Remarks: N/A



Distance: 201.9 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



Image Report 4/Page

Pipe Segment Refe	ere City	Street	Material		Location C	Sewer Use				
A6-23_A6-22	Oliver Springs	708 Hen Valley Rd.	Concrete F	Concrete Pipe (non		Concrete Pipe (non		Concrete Pipe (non		Sanitary
Upstream MH	Total Length	Year Laid	Sh	Shape		Details				
A6-23	203		Circ	Circular		Circular		of road		
DS Manhole	Length surveyed	Year Renewed	Height	Height Width						
A6-22	203		8	8	4					



Distance: 203.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A6-22



PACP Conditions

Pipe Segme	Pipe Segment Refere City		Street	Ma	terial	Location C	Sewer Use		
A6-23_	_A6-22	Oliver	Springs	708 Hen Valley Rd.	Concrete Pipe (non		Light High	Sanitary	
Upstrea	am MH	Total I	Length	Year Laid	Sh	ape	Location	n Details	
A6-	-23	20	03		Circ	cular	Middle	of road	
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Pipe Joint		
A6-	-22	20	03		8	8 8			
SPR	N/A	MPR	1	PO Number			Customer		
SPRI	N/A	MPRI	1	4397-03		GRW			
SFRI	IN/A	IVIFKI	ı	Work Order		Purpose			
QSR	N/A	QMR	1100	4397-02		Pre-	Rehabilitation S	ehabilitation Survey	
OF	PR	Surve	Surveyed By Direction		D	Date		a label	
1	1 Dustin		Downstream	20150807					
OP	OPRI Certificate Number		Pre-Cleaning	Ti	Time				
1	1 U-214-06020262		Jetting	13:57		Dry			
		Date C	leaned	End Time		Additional Info			
		2015	0807	14:12					

	Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
	1	0	0	1	1	1	1	1	1
	2	0	0	2	0	0	2	0	0
	3	0	0	3	0	0	3	0	0
	4	0	0	4	0	0	4	0	0
	5	0	0	5	0	0	5	0	0
Code ID Length									
	Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY	Struct	ipe Rating ural Index ick Rating	0 0 0000	0	pe Rating &M Index ick Rating	1 1.0 1100	Overall Pipe Rating Overall Index		1 1.0 1100