505-341-0109



## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	Material		Sewer Use		
A6-5_A6-4		Oliver Springs		Main St	Ductile	<b>Ductile Iron Pipe</b>		Sanitary		
Upstream MH		Total Length		Year Laid	Shape		Location	n Details		
A6-5		69.8			Circ	cular				
DS Manhole		Length surveyed		Year Renewed	Height	Width	Pipe Joint			
A6-4		69.8			8	8	13			
SPR	N/A	MPR	N/A	PO Number	Customer					
0001			-	4397-03				GRW		
SPRI	N/A	MPRI	N/A	Work Order				Purpose		
QSR	N/A	QMR	N/A	4397-02		Pre	Pre-Rehabilitation Survey			
OF	PR	Surveyed By		Direction	Date		Media label			
N/	N/A		Gordon	Downstream	20150826					
OPRI		Certificate Number		Pre-Cleaning	Time		Weather			
N/A		U-615-07000491		Jetting	14:10		Dry			
Date Cleaned						End Time		Additional Info		
20150826						14:15				


Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Crada
Distance	Condition		1st	2nd	%	Joint	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A6-5								
0.0 ft.	Water Level				5				
68.0 ft.	Water Level				5				
69.8 ft.	Access Point Manhole				0				
Remarks:	A6-4								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Mat	erial	Location C	Sewer Use
A6-5_A6-4	Oliver Springs	Main St	Ductile Iron Pipe		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location Details	
A6-5	69.8		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A6-4	69.8		8	8	13	



Distance: 0.0 ft. Grade: (

Condition: Access Point Manhole

Remarks: A6-5



Distance: 0.0 ft. Grade: (

Condition: Water Level


Remarks: N/A



Distance: 68.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 69.8 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A6-4



## **PACP Conditions**

Pipe Segment Refere		City		Street	Material		Location C	Sewer Use	
A6-5_A6-4		Oliver Springs		Main St	Ductile Iron Pipe		Easement/R	Sanitary	
Upstream MH A6-5		Total Length 69.8		Year Laid	Shape Circular		Location Details		
DS Ma	DS Manhole A6-4		surveyed	Year Renewed	Height	Width	Pipe Joint		
A			0.8		8	8	13		
SPR	N/A	MPR	N/A	PO Number	per		Customer		
0001				<b>4397-03</b> Work Order		GRW			
SPRI	N/A	MPRI	N/A			Purpose			
QSR	N/A	QMR	N/A	4397-02		Pre	Pre-Rehabilitation Survey		
OI	PR	Surveyed By		Direction	Date		Media label		
N.	/A	Charlie Gordon		Downstream	20150826				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
N/A U-615-070004		7000491	Jetting 14		14:10				
		Date C	leaned		End Time		Additional Info		
		2015	0826		14	:15			

			Stru	ctural Rat	ings	0	& M Ratin	gs	Con	nbined Ra	tings
Normal Defects		Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	
			4			4			4		
			2	0	0	2	0	0	2	0	0
				0	0		0	0		0	0
			3	0	0	3	0	0	3	0	0
			4	0	0	4	0	0	4	0	0
			5	0	0	5	0	0	5	0	0
Continu	ous C	Defects									
Code	ID	Length									
			Subtotals	0		Subtotals	0		Subtotals	0	
SUMMARY		Pi	pe Rating	0	Pi	pe Rating	0	0 Overall P		0	
		Struct	ural Index	0	O&M Index		0	Overall Index		0	
			Str. Qu	ick Rating	0000	O&M Qui	ick Rating	0000	Ovrl. Qu	ick Rating	0000