

## **Defect Listing**

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A6-7_	A6-6A	Oliver	Springs	Tri-county boulevar	Fibreglass Reinforc		Easement/R	Sanitary	
Upstream MH Total Length		Year Laid	Sha	ape	Location	Details			
A6	6-7 249.1 Circular								
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Height Width Pipe Joint			
A6-	-6A	24	9.1		8	8	8 N/A		
SPR	N/A	MPR	2	PO Number			Customer		
0001				4397-03		GRW			
SPRI	N/A	MPRI	2	Work Order					
QSR	N/A	QMR	2100	4397-02	Pre		e-Rehabilitation Survey		
OF	PR	Surve	yed By	Direction	Date		Media label		
2	2	Charlie Gordon		Downstream	20150826				
OF	PRI	Certificate Number		Pre-Cleaning	Time		Weather		
2		U-615-07000491		Jetting	10:24		Damp		
		Date C	leaned		End Time		Addition	Additional Info	
		2015	0826		10	:37			

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		O
Distance	Condition	Cont. Dict.	1st	2nd	%	Jonn	At/From	То	Grade
0.0 ft.	Access Point Manhole				0				
Remarks:	A6-7								
0.0 ft.	Water Level				10				
241.3 ft.	Water Level Sag				15				2
246.9 ft.	Water Level				5				
249.1 ft.	Access Point Manhole				0				
Remarks:	A6-6A								





## **Image Report 4/Page**

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A6-7_A6-6A	Oliver Springs	Tri-county boulevar	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A6-7	249.1		Circ	ular		
DS Manhole	Length surveyed	Year Renewed	Height	Width	Pipe Joint	
A6-6A	249.1		8	8	N/A	



Distance: 0.0 ft. Grade: 0

Condition: Access Point Manhole

Remarks: A6-7



Distance: 0.0 ft. Grade: 0

Condition: Water Level

Remarks: N/A



Distance: 241.3 ft. Grade: 2

Condition: Water Level Sag

Remarks: N/A



Distance: 246.9 ft. Grade: 0

Condition: Water Level

Remarks: N/A

ITpipes 4921 Alexander Blvd Albuquerque, NM 505-341-0109



## Image Report 4/Page

Pipe Segment Refere	City	Street	Material		Location C	Sewer Use
A6-7_A6-6A	Oliver Springs	Tri-county boulevar	Fibreglass Reinforc		Easement/R	Sanitary
Upstream MH	Total Length	Year Laid	Shape		Location	Details
A6-7	249.1	249.1 Circular				
DS Manhole	Length surveyed	Year Renewed	Height Width		Pipe Joint	
A6-6A	249.1		8	8	N/A	ر ا



Distance: 249.1 ft. Grade: (

Condition: Access Point Manhole

Remarks: A6-6A



## **PACP Conditions**

Pipe Segment Refere		City		Street	Mat	erial	Location C	Sewer Use	
A6-7_	A6-6A	Oliver	Springs	Tri-county boulevar	Fibreglass Reinforc		Easement/R	Sanitary	
Upstream MH To		Total	Length	Year Laid	Sh	ape Location Det		Details	
A	6-7	24	9.1		Circular				
DS Ma	anhole	Length s	surveyed	Year Renewed	Height	Width	Width Pipe Joint		
A6	-6A	24	249.1 8 8		N/A				
SPR	N/A	MPR	2	PO Number			Customer		
0001				4397-03			GRW Purpose		
SPRI	N/A	MPRI	2	Work Order					
QSR	N/A	QMR	2100	4397-02	4397-02 Pr		re-Rehabilitation Survey		
Ol	PR	Surve	yed By	Direction	Date		Media label		
2	2	Charlie Gordon		Downstream	20150826				
OF	OPRI		e Number	Pre-Cleaning	Time		Weather		
2 U-615-07000491		Jetting	10:24		Damp				
		Date C	Cleaned		End Time Addi		Addition	nal Info	
		2015	0826	10:37					

		Structural Ratings			О	& M Ratin	gs	Con	nbined Ra	tings
Normal [	Defects	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating	Grade Rating	No. Occur.	Rating
					4			4		_
		2	0	0	2	0	0	2	0	0
			0	0		1	2		1	2
		3	0	0	3	0	0	3	0	0
		4	0	0	4	0	0	4	0	0
		5	0	0	5	0	0	5	0	0
Continuou	s Defects									
Code I	D Length									
		<u> </u>								
		Subtotals	0		Subtotals	1		Subtotals	1	
SUMMARY		Pi	pe Rating	0	   Pi	pe Rating	2	Overall P	pe Rating	2
		Struct	ural Index	0	0	&M Index	2.0	Overall Index		2.0
		Str. Qu	ick Rating	0000	O&M Qui	ick Rating	2100	Ovrl. Qu	ick Rating	2100