



Defect Listing

Pipe Segment Refere... A7-5_A7-4	City Oliver Springs	Street Lookout Ave	Material Ductile Iron Pipe	Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A7-5	Total Length 11.3	Year Laid	Shape Circular	Location Details	
DS Manhole A7-4	Length surveyed 11.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13


SPR 3	MPR N/A	PO Number 4397-03	Customer GRW
SPRI 3	MPRI N/A	Work Order 4397-02	Purpose Pre-Rehabilitation Survey
QSR 3100	QMR N/A		
OPR 3	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150831
OPRI 3	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 10:31
	Date Cleaned	End Time 10:36	Weather Dry
			Media label
			Additional Info

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A7-5									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
11.3 ft.	Displaced Brick				0	<input type="checkbox"/>	6		3
11.3 ft.	Survey Abandoned				0	<input type="checkbox"/>			
Remarks: CANNOT GO PASS DEPOSIT IN LINE									



Image Report 4/Page

Pipe Segment Refere... A7-5_A7-4	City Oliver Springs	Street Lookout Ave	Material Ductile Iron Pipe		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A7-5	Total Length 11.3	Year Laid	Shape Circular		Location Details	
DS Manhole A7-4	Length surveyed 11.3	Year Renewed	Height 8	Width 8	Pipe Joint...	13




Distance: 0.0 ft. Grade: 0
Condition: Access Point Manhole
Remarks: A7-5



Distance: 0.0 ft. Grade: 0
Condition: Water Level
Remarks: N/A



Distance: 11.3 ft. Grade: 3
Condition: Displaced Brick
Remarks: N/A



Distance: 11.3 ft. Grade: 0
Condition: Survey Abandoned
Remarks: CANNOT GO PASS DEPOSIT IN LINE



Pipe Segment Refere... A7-5_A7-4	City Oliver Springs	Street Lookout Ave	Material Ductile Iron Pipe		Location C... Easement/R...	Sewer Use Sanitary
Upstream MH A7-5	Total Length 11.3	Year Laid	Shape Circular		Location Details	
DS Manhole A7-4	Length surveyed 11.3	Year Renewed	Height 8	Width 8	Pipe Joint... 13	
SPR 3	MPR N/A	PO Number 4397-03		Customer GRW		
SPRI 3	MPRI N/A	Work Order 4397-02		Purpose		
QSR 3100	QMR N/A			Pre-Rehabilitation Survey		
OPR 3	Surveyed By Charlie_Gordon	Direction Downstream	Date 20150831		Media label	
OPRI 3	Certificate Number U-615-07000491	Pre-Cleaning No Pre-Cleaning	Time 10:31		Weather Dry	
Date Cleaned			End Time 10:36		Additional Info	

[illegible]